



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 NISSAN SUNNY**

**SV | 101,215 KM**

VIN: MDHBN7AD6PG308571

## **Car highlights**



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



### **Bluetooth**

Enjoy your drive with bluetooth

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Music System**















Enjoy your drive with music system



### **Amazing Comfort**







Power driver seat



Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 101215            |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             | Fuel Efficiency   | 15.4 km/L mileage    |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color Other |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number     | MDHBN7AD6PG308571 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |  |   |                     |
|--|--|---|---------------------|
|  <b>Comfort &amp; Convenience</b> |  |   |                     |
| Rear Armrest with cupholder  |  |  | Rear Defogger       |
| Steering Column Adjuster   |  |  |                     |
|  <b>Safety &amp; Security</b>     |  |   |                     |
| Parking Sensors Rear   |  |  | Reverse Camera      |
| Traction Control   |  |  | Airbag Driver Front |

|  |   |                     |   |
|--|---|---------------------|---|
| ABS  | ✓ | Central Locking     | ✓ |
| Child Safety Locking   | ✓ |                     |   |
|  <b>Entertainment</b> |   |                     |   |
| Bluetooth Player   | ✓ | Infotainment System | ✓ |
| USB player   | ✓ |                     |   |
|  <b>Exteriors</b>     |   |                     |   |
| Halogen Headlights   | ✓ |                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |   |  |   |
|-----------------|---|--|---|
| Front left door |  | Front right door                           |   |
|                 |   | Panel: Paint Defect, Paint Chip-off < 5mm, |  |
|                 |   | Low Visibility Dent < 30mm                 |   |

|                |   |   |   |
|----------------|---|---|---|
| Rear left door |  | Rear right door                             |   |
|                |   | Panel: Paint Defect, Low Visual Dent < 30mm |  |


### Fenders Condition

|             |   |                               |   |
|-------------|---|-------------------------------|---|
| Left Fender |  | Right Fender                  |   |
|             |   | Right Fender: Low Visual Dent |  |

### Quarter Panels Condition

|                    |   |                     |   |
|--------------------|---|---------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|---|---------------------|---|


### Front Bumper Condition

|  |   |
|--|---|
| Front Bumper                             |   |
| Moulding: Misaligned/ Not Properly Fixed |  |

### Rear Bumper Condition

|                                    |   |
|------------------------------------|---|
| Rear Bumper                        |   |
| Rear Bumper: Light Scuffing < 80mm |  |

### Hood Condition

|                                    |   |
|------------------------------------|---|
| Hood                               |   |
| Bonnet: Low Visibility Dent < 30mm |  |

### Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

### Pillars Condition

|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Left A Pillar               | ✓ | Right A Pillar               | ✓ |
| Left A to B Pillar Beading  | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             |   | Monogram                     | ✓ |
| Light Scuffing < 50mm       | ! |                              |   |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel








Airbags

|                          |   |                       |   |
|--------------------------|---|-----------------------|---|
| Airbags                  | ✓ |                       |   |
| Controls                 | ✓ | Cruise Control        | ✓ |
| Infotainment Display     | ✓ | OBD Connector         | ✓ |
| Music System             | ✓ | Camera                | ✓ |
| Lights                   |   |                       |   |
| Headlight                |   |                       |   |
| Left: Scuff Marks > 50mm | ! | Interior Lights       | ✓ |
| Tail Light Cluster       | ✓ | License Plate Light   | ✓ |
| Air Conditioning         |   |                       |   |
| AC Cooling               | ✓ | AC Switch             | ✓ |
| AC System Leaks          | ✓ | Center AC Vent        | ✓ |
| Front Right AC Vent      | ✓ | Heater                | ✓ |
| Parking Sensors          | ✓ | Rear Defogger         | ✓ |
| USB Charging Port        | ✓ | Power/ Manual Windows | ✓ |

## Interiors & Luggage

|                                |   |                      |   |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console      | ✓ |
| Cup Holder                     | ✓ | Glove Box            | ✓ |
| Steering Wheel                 | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                     | ✓ | Head Rest            | ✓ |
| Door Controls And Trim         | ✓ | Grab Handle          | ✓ |
| Carpet                         | ✓ | Headliner            | ✓ |
| Rear View Mirror               | ✓ | Toolkit              | ✓ |



|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Tyres Condition            |   |                           |   |
| Left Hand Side Front Tyre  |  | Left Hand Side Rear Tyre  |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |   |
| Life remaining             |   |                           |   |
| LHS Front Tyre             | <55%  | LHS Rear Tyre             | <65%  |
| RHS Front Tyre             | <55%  | RHS Rear Tyre             | <75%  |
| Spare Tyre                 | <75%  |                           |   |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE