



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 JEEP WRANGLER

SAHARA | 42,098 KM

VIN: 1C4HJXBG5NW201691

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play















Enjoy your drive with apple play



Amazing Comfort











Power driver seat



Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 42098 |  Specs | Yes |
|  Engine | 3.6L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Four Wheel Drive |
|  Body Type | SUV | Fuel Efficiency | 9.1 km/L mileage |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Green |
|  Interior Trim | Fabric Trim |  Number of Airbags | 4 Airbags |
|  Seating Capacity | 4 Seats |  Number of keys | 1 Keys |
|  VIN number | 1C4HJXBG5NW201691 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|--------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Steering Mounted Audio Controls |  | Rear Defogger |  |
| Central Armrest |  | Remote Engine Start |  |
| Automatic Headlights |  | Steering Column Adjuster |  |
|  Exteriors | | | |

| | | | |
|--|---|----------------------|---|
| Fog Light Front | ✓ | Running Lights | ✓ |
| LED Headlights | ✓ | | |
|  Safety & Security | | | |
| Navigation | ✓ | Parking Sensors Rear | ✓ |
| Reverse Camera | ✓ | Blind Spot Monitor | ✓ |
| Traction Control | ✓ | Airbag Driver Front | ✓ |
| ABS | ✓ | Central Locking | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | USB Charging Port | ✓ |
| Infotainment System | ✓ | USB player | ✓ |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door



Front right door



Fenders Condition

Left Fender



Right Fender

Right Fender: Fender liner minor damage



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Right C Pillar Trim



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



Wheel cover



Antenna



Grill Condition



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



| | | | |
|-------------------------------|---|--------------------|---|
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| 4*4 Condition (If Applicable) | ✓ | Transmission Fluid | ✓ |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Suspension | | | |
| Shock Absorbers | ✓ | | |

Electricals, Controls & Lights

| | | | |
|-------------------|---|----------------------|---|
| Keys | | | |
| Master Key | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Cruise Control | ✓ | Infotainment Display | ✓ |
| OBD Connector | ✓ | Radar (If Equipped) | ✓ |
| Navigation System | ✓ | Music System | ✓ |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |

| | | | |
|-----------------------|---|-------------------------|---|
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |



Interiors & Luggage

| | | | |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Glove Box | ✓ | Steering Wheel | ✓ |
| Sunvisor | ✓ | Seat Upholstery | ✓ |
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Head Rest | ✓ | Door Controls And Trim | ✓ |
| Grab Handle | ✓ | Carpet | ✓ |
| Headliner | ✓ | Rear View Mirror | ✓ |
| Toolkit | ✓ | | |



Tyres

| | | | |
|----------------------------|---|---------------------------|---|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |

| | | | |
|----------------|------|---------------|------|
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <75% |
| Spare Tyre | <75% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE