



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.



2023 MG HS

LUXURY TROPHY | 77,703 KM

VIN: LSJA24W95PN026584

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Apple play


Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details



Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
360 degree Camera	✓	Parking Sensors Rear	~
Reverse Camera	✓	Traction Control	~
Front Camera	✓	Side Camera	
Airbag Curtain Shield	✓	Airbag Driver Front	~
ABS	✓	Central Locking	✓

Child Safety Locking	~		
Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Rear Armrest with cupholder	✓	Steering Mounted Audio Controls	•
Power Folding Mirrors	•	Power Tailgate/ Power Trunk	•
Rear Defogger	✓	Central Armrest	✓
Automatic Headlights	✓	Steering Column Adjuster	✓
Exteriors			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	LED Headlights	✓
Performance			
Hill Descent Control	✓		
⊈ s Entertainment			
Bluetooth Player	•	Apple Play	✓
Android Auto Play	•	USB Charging Port	~
Infotainment System		USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left B Pillar Trim	✓	Left B to C Pillar Beading	~
Right C Pillar Trim	~	Right B to C Pillar	•
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	•
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	•
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	•
Spare Alloy/ Rim Condition	✓		
Antenna	•	Grill Condition	✓
Monogram	~	Window Glass	•
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission			
Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓
Steering, Suspension & Brakes			
Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		
Electricals, Controls & Lights			
Keys			
Master Key			
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			

Airbags	✓		
Controls	✓	Cruise Control	•
Heads Up Display	✓	Infotainment Display	✓
OBD Connector	✓	Navigation System	•
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	~	Daylight Running Lights Right DRL: Low Brightness	(!)
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	•
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
USB Charging Port	•	Power/ Manual Windows	•
Memory Seats	~		
🖺 Interiors & Luggage			
Dashboard And Instrument Panel	•	Central Console	•
Cup Holder	•	Glove Box	•
Steering Wheel	✓	Sunvisor	•
Seat Upholstery	✓	Manual Seat Movement	•

Seat Belts	✓	Head Rest	•
Door Controls And Trim	✓	Grab Handle	•
Carpet	•	Headliner	✓
Rear View Mirror	✓	Toolkit	✓
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	~	Right Hand Side Rear Tyre	✓
Spare Tyre	•		
Life remaining			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE