



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 FORD TERRITORY

TREND | 46,223 KM

VIN: LJXCU3BB2RTF13090

## Car highlights



### Boosted Engine

This car has a Boosted Engine



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 46223             |  Specs             | Yes                 |
|  Engine           | 1.8L              |  Option Type       | Basic               |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SUV               |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 4 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | LJXCU3BB2RTF13090 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                 |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                 |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                  |  |
| Rear Armrest with cupholder                                                                                          |  | Steering Mounted Audio Controls |  |
| Rear Defogger                                                                                                        |  | Central Armrest                 |  |
| Steering Column Adjuster                                                                                             |  |                                 |                                                                                       |
|  <b>Exteriors</b>                 |                                                                                     |                                 |                                                                                       |

|                                                                                                                |   |                      |   |
|----------------------------------------------------------------------------------------------------------------|---|----------------------|---|
| Fog Light Front                                                                                                | ✓ | Roof Rails           | ✓ |
| Running Lights                                                                                                 | ✓ | LED Headlights       | ✓ |
|  <b>Safety &amp; Security</b> |   |                      |   |
| Parking Sensors Rear                                                                                           | ✓ | Reverse Camera       | ✓ |
| Blind Spot Monitor                                                                                             | ✓ | Traction Control     | ✓ |
| Airbag Driver Front                                                                                            | ✓ | ABS                  | ✓ |
| Central Locking                                                                                                | ✓ | Child Safety Locking | ✓ |
|  <b>Entertainment</b>         |   |                      |   |
| Bluetooth Player                                                                                               | ✓ | Apple Play           | ✓ |
| USB Charging Port                                                                                              | ✓ | Infotainment System  | ✓ |
| USB player                                                                                                     | ✓ |                      |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door



Front right door

Panel: Paint Chip-off < 5mm, Low Visibility  
Dent < 30mm



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm



### Fenders Condition

Left Fender

Condition: Low Visual Dent



Right Fender

Right Fender: Low Visual Dent



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm



### Trunk Condition

Trunk



Trunk conditon

Trunk



### Roof Condition

Roof



### Pillars Condition

Left A Pillar



Right A Pillar



|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Left A to B Pillar Beading  | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             | ✓ | Monogram                     | ✓ |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

|                      |   |                         |   |
|----------------------|---|-------------------------|---|
| Airbags              | ✓ |                         |   |
| Controls             | ✓ | Cruise Control          | ✓ |
| Infotainment Display | ✓ | OBD Connector           | ✓ |
| Music System         | ✓ | Camera                  | ✓ |
| Lights               |   |                         |   |
| Headlight            | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster   | ✓ | Daylight Running Lights | ✓ |
| License Plate Light  | ✓ | Fog Lights              | ✓ |
| Air Conditioning     |   |                         |   |
| AC Cooling           | ✓ | AC Switch               | ✓ |
| AC System Leaks      | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent  | ✓ | Heater                  | ✓ |
| Rear Blower Switch   | ✓ |                         |   |
| Parking Sensors      | ✓ | Rear Defogger           | ✓ |
| USB Charging Port    | ✓ | Power/ Manual Windows   | ✓ |

## Interiors & Luggage

|                                         |   |                      |   |
|-----------------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel          | ✓ | Central Console      | ✓ |
| Cup Holder                              | ✓ | Glove Box            | ✓ |
| Steering Wheel                          | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                         | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                              | ✓ | Head Rest            | ✓ |
| Door Controls And Trim                  | ✓ | Grab Handle          | ✓ |
| Carpet                                  |   | Headliner            | ✓ |
| Front Left Floor Mat: Smudge/Burn/Crack | ! |                      |   |

Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<75%

RHS Front Tyre

<55%

RHS Rear Tyre

<65%

Spare Tyre

<65%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE