



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 MITSUBISHI ATTRAGE GLX HIGHLINE | 107,209 KM

VIN: MMDAFT6J8NH004649

Car highlights

Fuel Efficient

Fuel efficient with 20.2 km/L



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat


Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.






150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Pillars Condition Left A Pillar Right A Pillar Left A to B Pillar Beading Right A to B Pillar Beading Right A to B Pillar Left B Pillar Left B Pillar Trim Left B to C Pillar Beading Right C Pillar Trim Right B to C Pillar Left C Pillar Right B to C Pillar Beading **Running Board Condition** Left Running Board Right Running Board Windshield Condition Front Windshield Rear Windshield Structural Assessment **Chassis Condition** Apron **Boot Floor** Firewall Condition Cowl Top **Head Light Support Condition** Cowl Top Cowl Top Rear View Mirror Condition Left Hand Side Mirror Left Side Mirror Right Side Mirror Alloy Wheel/ Rim Left Front Alloy/ Rim Left Rear Alloy/ Rim Right Front Alloy/ Rim Right Rear Alloy/ Rim Spare Alloy/ Rim Condition Wheel cover Antenna **Grill Condition** Monogram Light Scuffing < 50mm Window Glass Wiper

Panel Condition			
Rear Trunk Panel	✓		
Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		
Steering, Suspension & Brakes			
Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		
Electricals, Controls & Lights			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			



Tyres Tyres Condition Left Hand Side Front Tyre Left Hand Side Rear Tyre Right Hand Side Front Tyre Right Hand Side Rear Tyre Spare Tyre Life remaining LHS Front Tyre <85% LHS Rear Tyre <55% RHS Front Tyre <85% RHS Rear Tyre <55% Spare Tyre <65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE