


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2019 HONDA CIVIC**

**LX SPORT | 108,061 KM**

VIN: NLAFC5670KW000542

## Car highlights

### Fuel Efficient

Fuel efficient with 17.0 km/L

### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

### Bluetooth

Enjoy your drive with bluetooth

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 108061 | Specs | Yes |
| Engine | 1.6L | Option Type | Semi Loaded |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | SEDAN | Fuel Efficiency | 17.0 km/L mileage |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color White |
| Interior Trim | Fabric Trim | Number of Airbags | 2 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 1 Keys |
| VIN number | NLAFC5670KW000542 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Comfort & Convenience | | | |
|---|---|---|---|
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Rear Armrest with cupholder | ✓ | Steering Mounted Audio Controls | ✓ |
| Rear Defogger | ✓ | Central Armrest | ✓ |
| Remote Engine Start | ✓ | Steering Column Adjuster | ✓ |

**Exteriors**

| | | | |
|---|---|---|---|
| Fog Light Front | ✓ | Running Lights | ✓ |
| Rear Bumper Spoiler | ✓ | Halogen Headlights | ✓ |
| **Performance** | | | |
| Paddle Shift | ✓ | | |
| **Safety & Security** | | | |
| Parking Sensors Rear | ✓ | Traction Control | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed** ✓

## Exterior

### Doors condition

| | |
|---|---|
| Front left door ✓ | Front right door<br>Weather Strip: Minor Rubber Fare Use Wear ! |
| Rear left door<br>Panel: Dent ! | Rear right door<br>Weather Strip: Minor Fair Use Rubber Wear ! |

### Fenders Condition

| | |
|---|---|
| Left Fender ✓ | Right Fender<br>Right Fender: Low Visual Dent, Paint Chip-off ! |

### Quarter Panels Condition

| | |
|---|---|
| Left Quarter Panel ✓ | Right Quarter Panel<br>Condition: Low Visual Dent, Light Scuffing ! |

### Front Bumper Condition

Front Bumper ✓

### Rear Bumper Condition

Rear Bumper<br>Rear Bumper: Paint Faded !

### Hood Condition

Hood ✓

### Trunk Condition

Trunk ✓

### Trunk conditon

Trunk ✓

### Roof Condition

Roof ✓

### Pillars Condition

| | |
|---|---|
| Left A Pillar ✓ | Right A Pillar ✓ |

| | | | |
|---|---|---|---|
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |

### Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board<br>Condition: Scuffing | ! | Right Running Board | ✓ |

### Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

### Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor<br>Condition: Rear End Panel Repaired | ! | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |

### Cowl Top

| | |
|---|---|
| Cowl Top | ✓ |

### Rear View Mirror Condition

| | | | |
|---|---|---|---|
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |

### Alloy Wheel/ Rim

| | | | |
|---|---|---|---|
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |

| | | | |
|---|---|---|---|
| Wheel cover | ✓ | Grill Condition | ✓ |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |

### Panel Condition

Rear Trunk Panel ✓

## Engine & Transmission

### Engine

| | | | |
|---|---|---|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |

### Fuel System

| | |
|---|---|
| Fuel Tank | ✓ |

### Transmission Operation

| | | | |
|---|---|---|---|
| Gear Shifting | ✓ | Gear shift | ✓ |
| Drive Axle | ✓ | Transmission Fluid | ✓ |

## Steering, Suspension & Brakes

### Steering

| | |
|---|---|
| Steering wheel | ✓ |

### Brake System

| | | | |
|---|---|---|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |

### Suspension

| | |
|---|---|
| Shock Absorbers | ✓ |

## Electricals, Controls & Lights

### Keys

| | |
|---|---|
| Master Key | ✓ |

### Door Locks

| | |
|---|---|
| Child Safety Locking | ✓ |

### Dashboard

| | |
|---|---|
| Instrument Panel | ✓ |

### Airbags

| | | | |
|---|---|---|---|
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Music System | ✓ | | |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel<br>Color Faded | ! | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |

| | | | |
|---|---|---|---|
| Rear View Mirror | ✓ | Toolkit | ✓ |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <65% | LHS Rear Tyre | <45% |
| RHS Front Tyre | <55% | RHS Rear Tyre | <55% |
| Spare Tyre | <75% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE