



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 MINI COOPER S**

**IMPRESS | 34,841 KM**

VIN: WMW51DH07P2T11497

## **Car highlights**

### **Service History**

Service history available



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**
















Enjoy your drive with apple play



### **Amazing Comfort**











Power driver seat

Basic Details

 Kilometers	34841	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Beige
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	4 Seats	 Number of keys	1 Keys
 VIN number	WMW51DH07P2T11497		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Heads up Display		Climate Control AC	
Cruise Control		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest		Automatic Headlights	
Steering Column Adjuster			



## Safety & Security

Lane Departure Warning  
System



Navigation



Parking Sensors Front



Parking Sensors Rear



Auto Park Assist



Reverse Camera



Collision Warning System



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



## Performance

Paddle Shift



## Exteriors

Running Lights



Rear Bumper Spoiler



LED Headlights



## Entertainment

Bluetooth Player



Apple Play



Infotainment System



USB player























# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition			
Front left door		Front right door	
Fenders Condition			
Left Fender		Right Fender	
Quarter Panels Condition			
Left Quarter Panel		Right Quarter Panel Condition: Low Visual Dent	
Front Bumper Condition			
Front Bumper			
Rear Bumper Condition			
Rear Bumper			
Hood Condition			
Hood			
Trunk Condition			
Trunk			
Trunk conditon			
Trunk			
Roof Condition			
Roof			
Pillars Condition			
Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Right C Pillar Trim	

## Running Board Condition

Left Running Board



Right Running Board



## Sunroof Glass Condition (If Equipped)

Sun Roof Glass



## Windshield Condition

Front Windshield



Rear Windshield



## Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



## Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Antenna



Grill Condition



Monogram



Window Glass



Wiper



## Panel Condition

Rear Trunk Panel



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Cruise Control	✓	Heads Up Display	✓
Infotainment Display	✓	OBD Connector	✓
Navigation System	✓	Music System	✓
Sunroof Operation			
Sunroof	✓		

## Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Life remaining



LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE