



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 FORD ECOSPORT

AMBIENTE | 99,726 KM

VIN: MAJFK1BZ4JAE39759

Car highlights



Bluetooth

Enjoy your drive with bluetooth



Steering Mounted Audio Controls

Enjoy your drive with steering mounted audio controls

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Amazing Comfort















Power driver seat



Airbag safety










Airbag Driver Front







Basic Details

 Kilometers	99726	 Specs	Yes
 Engine	1.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	Fuel Efficiency	14.7 km/L mileage
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MAJFK1BZ4JAE39759		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security				
Traction Control			Airbag Driver Front	
ABS			Central Locking	
Child Safety Locking				
 Comfort & Convenience				
Steering Mounted Audio Controls			Rear Defogger	















Steering Column Adjuster		
 Entertainment		
Bluetooth Player		USB player 
 Exteriors		
Halogen Headlights		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition			
Front left door		Front right door	
		Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	
Rear left door		Rear right door	
Panel: Dent		Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	
Fenders Condition			
Left Fender		Right Fender	
Condition: Light Scuffing		Right Fender: Light Scuffing, Low Visual Dent	
Quarter Panels Condition			
Left Quarter Panel		Right Quarter Panel	
Front Bumper Condition			
Front Bumper			
Rear Bumper Condition			
Rear Bumper			
Hood Condition			
Hood			
Bonnet: Light Scuffing < 50mm			
Trunk Condition			
Trunk			
Trunk conditon			
Trunk			
Roof Condition			
Roof			
Pillars Condition			

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Beading: Mouldings Crack/ Fair Use Wear > 50mm	⚠	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓

Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags	✓		
Controls	✓	Infotainment Display	✓
OBD Connector	✓	Music System	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel			
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Central Console	✓
Glove Box	✓	Steering Wheel	!
		Steering Wheel Fair Use Wear	
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	!
		Front Left Floor Mat: Smudge/Burn/Crack	
Headliner			
Front Left: Light Smudge/Disfiguration	!	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE