



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 MAZDA CX 5

GL | 71,230 KM

VIN: JM7KFAWL1R0101839

## Car highlights



### Good Tyre Condition

Tyre age less than 2 years



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 71230             |  Specs             | Yes                 |
|  Engine           | 2.5L              |  Option Type       | Basic               |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SUV               |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 6 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | JM7KFAWL1R0101839 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                 |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                 |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                  |  |
| Rear Armrest with cupholder                                                                                          |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors                                                                                                |  | Rear Defogger                   |  |
| Central Armrest                                                                                                      |  | Steering Column Adjuster        |  |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                 |                                                                                       |

|                                                                                                        |   |                       |   |
|--------------------------------------------------------------------------------------------------------|---|-----------------------|---|
| Parking Sensors Rear                                                                                   | ✓ | Reverse Camera        | ✓ |
| Traction Control                                                                                       | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front                                                                                    | ✓ | ABS                   | ✓ |
| Central Locking                                                                                        | ✓ | Child Safety Locking  | ✓ |
|  <b>Exteriors</b>     |   |                       |   |
| Rear Bumper Spoiler                                                                                    | ✓ | LED Headlights        | ✓ |
|  <b>Entertainment</b> |   |                       |   |
| Bluetooth Player                                                                                       | ✓ | Apple Play            | ✓ |
| Android Auto Play                                                                                      | ✓ | USB Charging Port     | ✓ |
| Infotainment System                                                                                    | ✓ | USB player            | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

|                                             |                                                                                     |                                                  |                                                                                       |
|---------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------|---------------------------------------------------------------------------------------|
| Doors condition                             |                                                                                     |                                                  |                                                                                       |
| Front left door                             |    | Front right door<br>Panel: Light Scuffing < 50mm |    |
| Rear left door                              |    | Rear right door<br>Panel: Light Scuffing < 50mm  |    |
| Fenders Condition                           |                                                                                     |                                                  |                                                                                       |
| Left Fender                                 |    | Right Fender                                     |    |
| Quarter Panels Condition                    |                                                                                     |                                                  |                                                                                       |
| Left Quarter Panel                          |    | Right Quarter Panel<br>Condition: Light Scuffing |    |
| Front Bumper Condition                      |                                                                                     |                                                  |                                                                                       |
| Front Bumper                                |  |                                                  |                                                                                       |
| Rear Bumper Condition                       |                                                                                     |                                                  |                                                                                       |
| Rear Bumper<br>Rear Bumper: Scuffing > 80mm |  |                                                  |                                                                                       |
| Hood Condition                              |                                                                                     |                                                  |                                                                                       |
| Hood                                        |  |                                                  |                                                                                       |
| Trunk Condition                             |                                                                                     |                                                  |                                                                                       |
| Trunk                                       |  |                                                  |                                                                                       |
| Trunk conditon                              |                                                                                     |                                                  |                                                                                       |
| Trunk                                       |  |                                                  |                                                                                       |
| Roof Condition                              |                                                                                     |                                                  |                                                                                       |
| Roof                                        |  |                                                  |                                                                                       |
| Pillars Condition                           |                                                                                     |                                                  |                                                                                       |
| Left A Pillar                               |  | Right A Pillar                                   |  |
| Left A to B Pillar Beading                  |  | Right A to B Pillar Beading                      |  |

|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             |   | Monogram                     | ✓ |
| Scuffing > 50mm             | ! |                              |   |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



|                                                             |   |                     |   |
|-------------------------------------------------------------|---|---------------------|---|
| Controls                                                    | ✓ | Cruise Control      | ✓ |
| Infotainment Display                                        | ✓ | OBD Connector       | ✓ |
| Navigation System<br>Condition: Available - SD Card Missing | ! | Music System        | ✓ |
| Camera                                                      | ✓ |                     |   |
| Lights                                                      |   |                     |   |
| Headlight                                                   | ✓ | Interior Lights     | ✓ |
| Tail Light Cluster                                          | ✓ | License Plate Light | ✓ |
| Air Conditioning                                            |   |                     |   |
| AC Cooling                                                  | ✓ | AC Switch           | ✓ |
| AC System Leaks                                             | ✓ | Center AC Vent      | ✓ |
| Front Right AC Vent                                         | ✓ | Heater              | ✓ |
| Rear Blower Switch                                          | ✓ |                     |   |
| Rear Defogger                                               | ✓ | USB Charging Port   | ✓ |
| Power/ Manual Windows                                       | ✓ |                     |   |

## Interiors & Luggage

|                                |   |                      |   |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console      | ✓ |
| Cup Holder                     | ✓ | Glove Box            | ✓ |
| Steering Wheel                 | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                     | ✓ | Head Rest            | ✓ |
| Door Controls And Trim         | ✓ | Grab Handle          | ✓ |
| Carpet                         | ✓ | Headliner            | ✓ |
| Rear View Mirror               | ! | Toolkit              | ✓ |

## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<75%

Spare Tyre

<55%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE