



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 MAZDA 6

S | 74,580 KM

VIN: JM7GL4S33P1483269

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat

Basic Details

| | | | |
|--|-------------------|---|---------------------|
|  Kilometers | 74580 |  Specs | Yes |
|  Engine | 2.5L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN | Fuel Efficiency | 12.8 km/L mileage |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Grey |
|  Interior Trim | Fabric Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | JM7GL4S33P1483269 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Rear Armrest with cupholder |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors |  | Rear Defogger |  |
| Central Armrest |  | Steering Column Adjuster |  |
|  Safety & Security | | | |

| | | | |
|--|---|-----------------------|---|
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Traction Control | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Exteriors | | | |
| Running Lights | ✓ | LED Headlights | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | USB player | ✓ |





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|---|---|
| Front left door |  | Front right door Panel: Light Scuffing < 50mm |  |
| Rear left door |  | Rear right door Panel: Light Scuffing < 50mm, Paint Defect |  |

Fenders Condition

| | | | |
|--|---|--|---|
| Left Fender Condition: Light Scuffing, Paint Chip-off |  | Right Fender Right Fender: Light Scuffing |  |
|--|---|--|---|


Quarter Panels Condition

| | | | |
|--------------------|--|--|--|
| Left Quarter Panel |  | Right Quarter Panel Condition: Light Scuffing |  |
|--------------------|--|--|--|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper Rear Bumper: Light Scuffing < 80mm |  |
|---|---|

Hood Condition

| | |
|---|---|
| Hood Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm |  |
|---|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|-----------------------------|---|------------------------------|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | | Monogram | ✓ |
| Light Scuffing < 50mm | ! | | |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

| | | | |
|----------------------|---|-------------------------|---|
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Music System | ✓ | Camera | ✓ |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |

Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<55%

RHS Front Tyre

<45%

RHS Rear Tyre

<55%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE