



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2021 MAZDA 3**

**ALLURE | 48,327 KM**

VIN: JM7BPAH78M1114894

## **Car highlights**

### **Service History**

Service history available



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**
















Enjoy your drive with apple play



### **Amazing Comfort**











Power driver seat

Basic Details

|  |                   |   |                    |
|--|-------------------|---|--------------------|
|  Kilometers       | 48327             |  Specs             | Yes                |
|  Engine           | 2.0L              |  Option Type       | Fully Loaded       |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive  |
|  Body Type        | HATCHBACK         |  Fuel              | Petrol             |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Red |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 7 Airbags          |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys             |
|  VIN number     | JM7BPAH78M1114894 |   |                    |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Comfort & Convenience       |  |   |  |
|---|--|---|--|
| Climate Control AC           |  | Cruise Control                   |  |
| Rear Armrest with cupholder  |  | Steering Mounted Audio Controls  |  |
| Power Folding Mirrors        |  | Rear Defogger                    |  |
| Central Armrest              |  | Automatic Headlights             |  |
| Steering Column Adjuster     |  |   |  |



## Safety & Security

Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Knees



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Exteriors

Running Lights



LED Headlights



## Entertainment

Bluetooth Player



Apple Play



Android Auto Play



Infotainment System



USB player







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|   |   |   |   |
|---|---|---|---|
| Front left door                         |  | Front right door<br>Panel: Light Scuffing < 50mm                      |  |
| Rear left door<br>Panel: Dent, Scuffing |  | Rear right door<br>Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm |  |

### Fenders Condition

|  |   |  |   |
|--|---|--|---|
| Left Fender<br>Condition: Light Scuffing |  | Right Fender<br>Right Fender: Light Scuffing |  |
|--|---|--|---|


### Quarter Panels Condition

|                    |   |  |   |
|--------------------|---|--|---|
| Left Quarter Panel |  | Right Quarter Panel<br>Condition: Light Scuffing |  |
|--------------------|---|--|---|

### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|   |   |
|---|---|
| Rear Bumper<br>Rear Bumper: Scuffing > 80mm |  |
|---|---|

### Hood Condition

|   |   |
|---|---|
| Hood<br>Bonnet: Scuffing > 50mm, Paint Chip-off < 5mm |  |
|---|---|

### Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

### Pillars Condition

|                                       |   |                              |   |
|---------------------------------------|---|------------------------------|---|
| Left A Pillar                         | ✓ | Right A Pillar               | ✓ |
| Left A to B Pillar Beading            | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar                   | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                | ✓ |
| Running Board Condition               |   |                              |   |
| Left Running Board                    | ✓ | Right Running Board          | ✓ |
| Sunroof Glass Condition (If Equipped) |   |                              |   |
| Sun Roof Glass                        | ✓ |                              |   |
| Windshield Condition                  |   |                              |   |
| Front Windshield                      | ✓ | Rear Windshield              | ✓ |
| Structural Assessment                 |   |                              |   |
| Chassis Condition                     | ✓ | Apron                        | ✓ |
| Boot Floor                            | ✓ | Firewall Condition           | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                              |   |                              |   |
| Cowl Top                              | ✓ |                              |   |
| Rear View Mirror Condition            |   |                              |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror                     | ✓ |                              |   |
| Alloy Wheel/ Rim                      |   |                              |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |                              |   |
| Antenna                               | ✓ | Grill Condition              | ! |
|                                       |   | Light Scuffing < 50mm        |   |
| Monogram                              | ✓ | Window Glass                 | ✓ |

|                  |   |  |
|------------------|---|--|
| Wiper            | ✓ |  |
| Panel Condition  |   |  |
| Rear Trunk Panel | ✓ |  |

## Engine & Transmission

|                                |   |                      |
|--------------------------------|---|----------------------|
| Engine                         |   |                      |
| Engine Body                    | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓     |
| Radiator Condition             | ✓ | Radiator Coolant ✓   |
| Fuel System                    |   |                      |
| Fuel Tank                      | ✓ |                      |
| Transmission Operation         |   |                      |
| Gear Shifting                  | ✓ | Drive Axle ✓         |
| Transmission Fluid             | ✓ |                      |

## Steering, Suspension & Brakes

|                        |   |                         |
|------------------------|---|-------------------------|
| Steering               |   |                         |
| Steering wheel         | ✓ |                         |
| Brake System           |   |                         |
| Parking Brake          | ✓ | Brake Master Cylinder ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid ✓           |
| Suspension             |   |                         |
| Shock Absorbers        | ✓ |                         |

## Electricals, Controls & Lights

|                      |   |
|----------------------|---|
| Keys                 |   |
| Master Key           | ✓ |
| Door Locks           |   |
| Child Safety Locking | ✓ |
| Dashboard            |   |

|                       |   |  |   |
|-----------------------|---|--|---|
| Instrument Panel      | ✓ |  |   |
| Airbags               |   |  |   |
| Airbags               | ✓ |  |   |
| Controls              | ✓ | Cruise Control                         | ✓ |
| Infotainment Display  | ✓ | OBD Connector                          | ✓ |
| Radar (If Equipped)   | ✓ | Navigation System                      | ! |
|                       |   | Condition: Available - SD Card Missing |   |
| Music System          | ✓ |  |   |
| Sunroof Operation     |   |  |   |
| Sunroof               | ✓ |  |   |
| Camera                | ✓ |  |   |
| Lights                |   |  |   |
| Headlight             | ✓ | Interior Lights                        | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights                | ✓ |
| License Plate Light   | ✓ |  |   |
| Air Conditioning      |   |  |   |
| AC Cooling            | ✓ | AC Switch                              | ✓ |
| AC System Leaks       | ✓ | Center AC Vent                         | ✓ |
| Front Right AC Vent   | ✓ | Heater                                 | ✓ |
| Rear Blower Switch    | ✓ |  |   |
| Rear Defogger         | ✓ | USB Charging Port                      | ✓ |
| Power/ Manual Windows | ✓ |  |   |

## Interiors & Luggage

|                                |   |                                     |   |
|--------------------------------|---|-------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console                     | ! |
|                                |   | Gear Shift Knob: Knob Fair Use Wear |   |
| Cup Holder                     | ✓ | Glove Box                           | ✓ |



|                              |   |                      |   |
|------------------------------|---|----------------------|---|
| Steering Wheel               | ⓘ | Sunvisor             | ✓ |
| Steering Wheel Fair Use Wear |   |                      |   |
| Seat Upholstery              | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                   | ✓ | Head Rest            | ✓ |
| Door Controls And Trim       | ✓ | Grab Handle          | ✓ |
| Carpet                       | ✓ | Headliner            | ✓ |
| Rear View Mirror             | ✓ | Toolkit              | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <75% | LHS Rear Tyre             | <65% |
| RHS Front Tyre             | <75% | RHS Rear Tyre             | <65% |
| Spare Tyre                 | <65% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE