



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 HYUNDAI CRETA**

**SMART | 32,966 KM**

VIN: MF3PB8121RJ108122

## **Car highlights**



### **Good Tyre Condition**

Tyre age less than 2 years



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**















Enjoy your drive with apple play



### **Amazing Comfort**










Power driver seat



Basic Details

 Kilometers	32966	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	Fuel Efficiency	14.8 km/L mileage
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MF3PB8121RJ108122		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest		Automatic Headlights	
Steering Column Adjuster			
 <b>Safety &amp; Security</b>			

Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 <b>Exteriors</b>			
Roof Rails	✓	Running Lights	✓
LED Headlights	✓		
 <b>Entertainment</b>			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm	
Rear left door		Rear right door	

### Fenders Condition

Left Fender Condition: Low Visual Dent, Light Scuffing		Right Fender Right Fender: Low Visual Dent	
---	---	---	---

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Dent	
--------------------	---	--	---

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
-------------	---

### Hood Condition

Hood	
------	---

### Trunk Condition

Trunk	
-------	---





### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	

Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition		Monogram	✓
Scuffing > 50mm	!		
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Parking Sensors	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Memory Seats	✓

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor Left: Sunvisor LHS Smudge	⚠
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓



## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<65%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE