



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 MG ZS**

**LUXURY TROPHY | 73,387 KM**

VIN: LSJW74C93PZ050483

## **Car highlights**



### **Manufacturer warranty**

Till 06/11/2027 (Not verified)



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**
















Enjoy your drive with apple play



### **Amazing Comfort**












Power driver seat





## Basic Details

 Kilometers	73387	 Specs	Yes
 Engine	1.3L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	LSJW74C93PZ050483		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Safety &amp; Security</b>			
360 degree Camera		Parking Sensors Rear	
Reverse Camera		Blind Spot Monitor	
Traction Control		Front Camera	
Side Camera		Airbag Curtain Shield	
Airbag Driver Front		ABS	

Central Locking	✓	Child Safety Locking	✓
 <b>Exteriors</b>			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
LED Headlights	✓		
 <b>Comfort &amp; Convenience</b>			
Cruise Control	✓	Steering Mounted Audio Controls	✓
Power Folding Mirrors	✓	Rear Defogger	✓
Central Armrest	✓	Automatic Headlights	✓
Steering Column Adjuster	✓		
 <b>Performance</b>			
Hill Descent Control	✓		
 <b>Entertainment</b>			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm	
Rear left door		Rear right door	

### Fenders Condition

Left Fender Condition: Low Visual Dent		Right Fender Right Fender: Low Visual Dent, Paint Chip-off	
---	---	---	---


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Low Visual Dent	
--------------------	---	---	---


### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm	
---	---

### Hood Condition

Hood Bonnet: Low Visibility Dent < 30mm, Paint Chip-off < 5mm	
---	---

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top		Head Light Support Condition	✓
Beading: Crack/Fair Use Wear<50mm	!		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	

Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			

Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Radar (If Equipped)	✓	Music System	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Headlight			
Right: Light Scuff Marks < 50mm	!	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	!
		Right DRL: Low Brightness	
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Parking Sensors	✓	Rear Defogger	!
		Extensive Wear Of Strip	
USB Charging Port	✓	Power/ Manual Windows	✓
Seat Heaters	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
--------------------------------	---	-----------------	---



Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	✓
Steering Wheel Fair Use Wear			
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet			
Front Left Floor Mat: Smudge/Burn/Crack, Floor Mat Lock Damage	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<75%
Spare Tyre	<45%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE