



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 VOLKSWAGEN TIGUAN**

**TREND | 94,355 KM**

VIN: WVGAE2AX6PW022729

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Front, Parking Sensors Rear

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 94355             |  Specs             | Yes                  |
|  Engine           | 1.4L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Green |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | WVGAE2AX6PW022729 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                   |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                   |                                                                                       |
| Cruise Control                                                                                                       |  | Power Window front - Drivers Side |  |
| Power Window front - Passenger Side                                                                                  |  | Power Windows Rear                |  |
|  <b>Performance</b>               |                                                                                     |                                   |                                                                                       |
| Paddle Shift                                                                                                         |  |                                   |                                                                                       |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                   |                                                                                       |

|                                                                                                        |   |                      |   |
|--------------------------------------------------------------------------------------------------------|---|----------------------|---|
| Parking Sensors Front                                                                                  | ✓ | Parking Sensors Rear | ✓ |
| Airbag Curtain Shield                                                                                  | ✓ | Airbag Driver Front  | ✓ |
| ABS                                                                                                    | ✓ |                      |   |
|  <b>Exteriors</b>     |   |                      |   |
| Running Lights                                                                                         | ✓ | Rear Bumper Spoiler  | ✓ |
|  <b>Entertainment</b> |   |                      |   |
| Bluetooth Player                                                                                       | ✓ | Apple Play           | ✓ |
| Android Auto Play                                                                                      | ✓ |                      |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

#### Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm



#### Rear left door



#### Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



### Fenders Condition

#### Left Fender

Condition: Light Scuffing



#### Right Fender



### Quarter Panels Condition

#### Left Quarter Panel



#### Right Quarter Panel

Condition: Light Scuffing, Dent



### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Dent < 50mm



### Hood Condition

#### Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm



### Running Board Condition

#### Left Running Board



#### Right Running Board



### Windshield Condition

#### Front Windshield



#### Rear Windshield



### Structural Assessment

#### Chassis Condition



#### Apron



#### Boot Floor



#### Firewall Condition



|                                          |   |                                                  |   |
|------------------------------------------|---|--------------------------------------------------|---|
| Head Light Support Condition             | ✓ |                                                  |   |
| Cowl Top                                 |   |                                                  |   |
| Cowl Top                                 | ✓ |                                                  |   |
| Alloy Wheel/ Rim                         |   |                                                  |   |
| Left Front Alloy/ Rim                    | ✓ | Left Rear Alloy/ Rim<br>Rim: Alloy Edge Scuffing | ! |
| Right Front Alloy/ Rim                   | ✓ | Right Rear Alloy/ Rim                            | ✓ |
| Grill Condition<br>Light Scuffing < 50mm | ! |                                                  |   |
| Panel Condition                          |   |                                                  |   |
| Rear Trunk Panel                         | ✓ |                                                  |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition | ✓ |
| Radiator Coolant               | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|            |   |
|------------|---|
| Keys       |   |
| Master Key | ✓ |

|                         |   |                      |   |
|-------------------------|---|----------------------|---|
| Dashboard               |   |                      |   |
| Instrument Panel        | ✓ |                      |   |
| Controls                | ✓ | Infotainment Display | ✓ |
| Music System            | ✓ |                      |   |
| Lights                  |   |                      |   |
| Headlight               | ✓ | Tail Light Cluster   | ✓ |
| Daylight Running Lights | ✓ |                      |   |
| Air Conditioning        |   |                      |   |
| AC Cooling              | ✓ | AC System Leaks      | ✓ |

## Interiors & Luggage

|                                |   |                                                |   |
|--------------------------------|---|------------------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel<br>Steering Wheel Fair Use Wear | ! |
| Headliner                      | ✓ | Toolkit                                        | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <90% | LHS Rear Tyre             | <90% |
| RHS Front Tyre             | <90% | RHS Rear Tyre             | <90% |
| Spare Tyre                 | <35% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE