



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



### **2024 VOLKSWAGEN GOLF**

GTI | 62,848 KM

VIN: WVWDH1CD0RW126755

# **Car highlights**



### **Boosted Engine**

This car has a Boosted Engine



#### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### Apple play


Enjoy your drive with apple play



### **Amazing Comfort**


Power driver seat

#### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Exteriors			
Fog Light Front	~	Running Lights	•
Rear Bumper Spoiler	~	LED Headlights	<b>✓</b>
Performance			
Paddle Shift	~		
∜ Safety & Security			
Parking Sensors Front	<b>✓</b>	Parking Sensors Rear	~
Reverse Camera	<b>✓</b>	Blind Spot Monitor	~
Traction Control	•	Airbag Curtain Shield	•
Airbag Driver Front	<b>✓</b>	ABS	•
Central Locking	~	Child Safety Locking	•
<b>□ ■ Entertainment</b>			
Bluetooth Player	<b>✓</b>	Apple Play	<b>✓</b>
Android Auto Play	<b>✓</b>	USB Charging Port	~
Infotainment System	<b>✓</b>	USB player	<b>✓</b>

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board	<b>✓</b>
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	<b>✓</b>		
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Apron	<b>~</b>
Boot Floor	<b>✓</b>	Firewall Condition	<b>✓</b>
Cowl Top	<b>✓</b>	Head Light Support Condition	<b>✓</b>
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Face Scuffing	(!)	Left Rear Alloy/ Rim	<b>✓</b>
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	<u>!</u>
Night Front Alloy/ Nilli		Rim: Alloy Edge/Scuffing	
Spare Alloy/ Rim Condition	<b>✓</b>		
Antenna	<b>✓</b>	Grill Condition Light Scuffing < 50mm	!
Monogram	<b>✓</b>	Window Glass	<b>✓</b>
Wiper	<b>✓</b>		

Panel Condition			
Rear Trunk Panel	<b>✓</b>		
Engine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>
Turbocharger/ Supercharger	<b>✓</b>	Radiator Condition	<b>✓</b>
Radiator Coolant	<b>✓</b>		
Fuel System			
Fuel Tank	<b>✓</b>		
Transmission Operation			
Gear Shifting	<b>✓</b>	Gear shift	<b>✓</b>
Drive Axle	<b>✓</b>	Transmission Fluid	<b>✓</b>
Steering, Suspension & Brakes			
Steering			
Steering wheel	<b>✓</b>		
Brake System			
Parking Brake	<b>✓</b>	Brake Master Cylinder	<b>✓</b>
Brake Disc & Brake Pad	<b>✓</b>	Brake Fluid	<b>✓</b>
Suspension			
Shock Absorbers	<b>✓</b>		
Electricals, Controls & Lights			
Keys			
Master Key	<b>✓</b>	Spare Key(s)	<b>✓</b>
Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			

Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>✓</b>		
Controls	<b>✓</b>	Cruise Control	<b>✓</b>
Infotainment Display	<b>✓</b>	OBD Connector	•
Radar (If Equipped)	<b>✓</b>	Navigation System	<b>✓</b>
Music System	<b>✓</b>		
Sunroof Operation			
Sunroof	<b>✓</b>		
Camera	<b>✓</b>		
Lights			
Headlight	<b>✓</b>	Interior Lights	<b>✓</b>
Tail Light Cluster	<b>✓</b>	Daylight Running Lights	<b>✓</b>
License Plate Light	<b>✓</b>	Fog Lights	<b>✓</b>
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	<b>✓</b>
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Front Right AC Vent	<b>✓</b>	Heater	<b>✓</b>
Rear Blower Switch	<b>✓</b>		
Rear Defogger	<b>✓</b>	USB Charging Port	<b>✓</b>
Power/ Manual Windows	<b>✓</b>		
🖺 Interiors & Luggage			
Dashboard And Instrument Panel	<b>✓</b>	Central Console	<b>✓</b>
Cup Holder	<b>✓</b>	Glove Box	•

Steering Wheel	<b>✓</b>	Sunvisor	<b>✓</b>
Seat Upholstery	<b>✓</b>	Manual Seat Movement	<b>~</b>
Seat Belts	<b>✓</b>	Head Rest	<b>✓</b>
Door Controls And Trim	•	Grab Handle	<b>✓</b>
Carpet	•	Headliner	<b>✓</b>
Rear View Mirror	•	Toolkit	<b>✓</b>
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	<b>✓</b>	Left Hand Side Rear Tyre	
		•	
Right Hand Side Front Tyre	<b>✓</b>	Right Hand Side Rear Tyre	<b>✓</b>
Right Hand Side Front Tyre  Spare Tyre	<ul><li></li><li></li></ul>		•
	<b>✓</b>		
Spare Tyre	<65%		<65%
Spare Tyre  Life remaining		Right Hand Side Rear Tyre	<65% <65%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE