



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 KIA SONET**

**EX | 20,810 KM**

VIN: MZBFC8144RN361029

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Apple play**

Enjoy your drive with apple play

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                    |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|--------------------|
|  Kilometers       | 20810             |  Specs             | Yes                |
|  Engine           | 1.5L              |  Option Type       | Fully Loaded       |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive  |
|  Body Type        | SUV               |  Fuel              | Petrol             |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Red |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 2 Airbags          |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys             |
|  VIN number     | MZBFC8144RN361029 |                                                                                                     |                    |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                 |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                 |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                  |  |
| Rear Armrest with cupholder                                                                                          |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors                                                                                                |  | Rear Defogger                   |  |
| Central Armrest                                                                                                      |  | Remote Engine Start             |  |
| Automatic Headlights                                                                                                 |  | Steering Column Adjuster        |  |



## Exteriors

Fog Light Front



Roof Rails



Running Lights



Rear Bumper Spoiler



LED Headlights



## Safety & Security

Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Entertainment

Bluetooth Player



Apple Play



Android Auto Play



USB Charging Port



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

|                 |                                                                                   |                              |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door             |  |
| Rear left door  |  | Rear right door              |  |
|                 |                                                                                   | Panel: Light Scuffing < 50mm |                                                                                     |

Fenders Condition

|             |                                                                                   |                              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|------------------------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender                 |  |
|             |                                                                                   | Right Fender: Paint Chip-off |                                                                                     |

Quarter Panels Condition

|                    |                                                                                   |                            |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel        |  |
|                    |                                                                                   | Condition: Low Visual Dent |                                                                                     |

Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

Rear Bumper Condition

|             |                                                                                     |
|-------------|-------------------------------------------------------------------------------------|
| Rear Bumper |  |
|-------------|-------------------------------------------------------------------------------------|

Hood Condition

|                              |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|
| Hood                         |  |
| Bonnet: Paint Chip-off < 5mm |                                                                                     |

Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

Pillars Condition

|                            |                                                                                     |                             |                                                                                       |
|----------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|
| Left A Pillar              |  | Right A Pillar              |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |

|                                       |   |                              |   |
|---------------------------------------|---|------------------------------|---|
| Right A to B Pillar                   | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                | ✓ |
| Running Board Condition               |   |                              |   |
| Left Running Board                    | ✓ | Right Running Board          | ✓ |
| Sunroof Glass Condition (If Equipped) |   |                              |   |
| Sun Roof Glass                        | ✓ |                              |   |
| Windshield Condition                  |   |                              |   |
| Front Windshield                      | ✓ | Rear Windshield              | ✓ |
| Structural Assessment                 |   |                              |   |
| Chassis Condition                     | ✓ | Apron                        | ✓ |
| Boot Floor                            | ✓ | Firewall Condition           | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                              |   |                              |   |
| Cowl Top                              | ✓ |                              |   |
| Rear View Mirror Condition            |   |                              |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror                     |   |                              |   |
| Body: Light Scuffing                  | ! |                              |   |
| Alloy Wheel/ Rim                      |   |                              |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |                              |   |
| Antenna                               | ✓ | Grill Condition              |   |
|                                       |   | Light Scuffing < 50mm        | ! |
| Monogram                              | ✓ | Window Glass                 | ✓ |
| Wiper                                 | ✓ |                              |   |
| Panel Condition                       |   |                              |   |

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

|                         |   |                         |   |
|-------------------------|---|-------------------------|---|
| Airbags                 | ✓ |                         |   |
| Controls                | ✓ | Cruise Control          | ✓ |
| Infotainment Display    | ✓ | OBD Connector           | ✓ |
| Music System            | ✓ |                         |   |
| Sunroof Operation       |   |                         |   |
| Sunroof                 | ✓ |                         |   |
| Camera                  | ✓ |                         |   |
| Lights                  |   |                         |   |
| Headlight               | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster      | ✓ | Daylight Running Lights | ✓ |
| License Plate Light     | ✓ | Fog Lights              | ✓ |
| Air Conditioning        |   |                         |   |
| AC Cooling              | ✓ | AC Switch               | ✓ |
| AC System Leaks         | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent     | ✓ | Heater                  | ✓ |
| Rear Blower Switch      | ✓ |                         |   |
| Rear Defogger           |   |                         |   |
| Extensive Wear Of Strip | ! | USB Charging Port       | ✓ |
| Power/ Manual Windows   | ✓ |                         |   |

## Interiors & Luggage

|                                |   |                      |   |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console      | ✓ |
| Cup Holder                     | ✓ | Glove Box            | ✓ |
| Steering Wheel                 | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                     | ✓ | Head Rest            | ✓ |



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<75%

RHS Front Tyre

<55%

RHS Rear Tyre

<75%

Spare Tyre

<85%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE