



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 MAZDA CX 5

GS | 94,954 KM

VIN: JM7KFAWL1K0232162

Car highlights



Cruise control

Cruise control to drive with ease & comfort

LED headlamp

This car has a LED headlamp

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	94954	 Specs	Yes
 Engine	2.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	JM7KFAWL1K0232162		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest		Steering Column Adjuster	
 Safety & Security			
Traction Control		Airbag Curtain Shield	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Entertainment			
Bluetooth Player		USB player	
 Exteriors			
LED Headlights			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm



Fenders Condition

Left Fender

Condition: Low Visual Dent



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Low Visual Dent



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Paint Faded, Colour Mismatch/ Low Brightness



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition		Monogram	✓
Light Scuffing < 50mm	!		
Window Glass	✓	Wiper	✓
Panel Condition			

Rear Trunk Panel	✓
------------------	---

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys	
Master Key	✓
Door Locks	
Child Safety Locking	✓
Dashboard	
Instrument Panel	✓
Airbags	

Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<85%	LHS Rear Tyre	<90%
RHS Front Tyre	<85%	RHS Rear Tyre	<90%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE