



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 SUZUKI BALENO**

**GL | 58,290 KM**

VIN: MBHWBAC14RG596582

## **Car highlights**

### **Fuel Efficient**

Fuel efficient with 17.2 km/L



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                       |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|-----------------------|
|  Kilometers       | 58290             |  Specs             | Yes                   |
|  Engine           | 1.5L              |  Option Type       | Basic                 |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive     |
|  Body Type        | HATCHBACK         | Fuel Efficiency                                                                                     | 17.2 km/L mileage     |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color Silver |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags             |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys                |
|  VIN number     | MBHWBAC14RG596582 |                                                                                                     |                       |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                       |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                       |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control        |  |
| Steering Mounted Audio Controls                                                                                      |  | Power Folding Mirrors |  |
| Rear Defogger                                                                                                        |  | Central Armrest       |  |
| Steering Column Adjuster                                                                                             |  |                       |                                                                                       |
|  <b>Safety &amp; Security</b>     |                                                                                     |                       |                                                                                       |

|                                                                                                        |   |                     |   |
|--------------------------------------------------------------------------------------------------------|---|---------------------|---|
| Parking Sensors Rear                                                                                   | ✓ | Reverse Camera      | ✓ |
| Traction Control                                                                                       | ✓ | Airbag Driver Front | ✓ |
| ABS                                                                                                    | ✓ | Central Locking     | ✓ |
| Child Safety Locking                                                                                   | ✓ |                     |   |
|  <b>Exteriors</b>     |   |                     |   |
| Rear Bumper Spoiler                                                                                    | ✓ | Halogen Headlights  | ✓ |
|  <b>Entertainment</b> |   |                     |   |
| Bluetooth Player                                                                                       | ✓ | Apple Play          | ✓ |
| Android Auto Play                                                                                      | ✓ | USB Charging Port   | ✓ |
| Infotainment System                                                                                    | ✓ | USB player          | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                                                  |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|--------------------------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door<br>Panel: Light Scuffing < 50mm |  |
|-----------------|-----------------------------------------------------------------------------------|--------------------------------------------------|-------------------------------------------------------------------------------------|

|                |                                                                                   |                 |                                                                                     |
|----------------|-----------------------------------------------------------------------------------|-----------------|-------------------------------------------------------------------------------------|
| Rear left door |  | Rear right door |  |
|----------------|-----------------------------------------------------------------------------------|-----------------|-------------------------------------------------------------------------------------|

### Fenders Condition

|                                           |                                                                                   |              |                                                                                     |
|-------------------------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender<br>Condition: Low Visual Dent |  | Right Fender |  |
|-------------------------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                   |                                                   |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------------------------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel<br>Condition: Low Visual Dent |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------------------------------------|-------------------------------------------------------------------------------------|

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                                                |                                                                                     |
|----------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper<br>Rear Bumper: Light Scuffing < 80mm, Dent < 50mm |  |
|----------------------------------------------------------------|-------------------------------------------------------------------------------------|

### Hood Condition

|                                                 |                                                                                     |
|-------------------------------------------------|-------------------------------------------------------------------------------------|
| Hood<br>Bonnet: Acid Marks/ Bird Dropping < 5mm |  |
|-------------------------------------------------|-------------------------------------------------------------------------------------|

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Pillars Condition

|               |                                                                                     |                |                                                                                       |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|
| Left A Pillar |  | Right A Pillar |  |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|

|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Left A to B Pillar Beading  | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             |   | Monogram                     | ✓ |
| Light Scuffing < 50mm       | ! |                              |   |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



|                      |   |                       |   |
|----------------------|---|-----------------------|---|
| Controls             | ✓ | Cruise Control        | ✓ |
| Infotainment Display | ✓ | OBD Connector         | ✓ |
| Music System         | ✓ | Camera                | ✓ |
| Lights               |   |                       |   |
| Headlight            | ✓ | Interior Lights       | ✓ |
| Tail Light Cluster   | ✓ | License Plate Light   | ✓ |
| Air Conditioning     |   |                       |   |
| AC Cooling           | ✓ | AC Switch             | ✓ |
| AC System Leaks      | ✓ | Center AC Vent        | ✓ |
| Front Right AC Vent  | ✓ | Heater                | ✓ |
| Rear Blower Switch   | ✓ |                       |   |
| Parking Sensors      | ✓ | Rear Defogger         | ✓ |
| USB Charging Port    | ✓ | Power/ Manual Windows | ✓ |



## Interiors & Luggage

|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console        | ✓ |
| Glove Box                      | ✓ | Steering Wheel         | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery        | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts             | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim | ✓ |
| Grab Handle                    | ✓ | Carpet                 | ✓ |
| Headliner                      | ✓ | Rear View Mirror       | ✓ |
| Toolkit                        | ✓ |                        |   |



## Tyres

|                            |                                                                                   |                           |                                                                                     |
|----------------------------|-----------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| Tyres Condition            |                                                                                   |                           |                                                                                     |
| Left Hand Side Front Tyre  |  | Left Hand Side Rear Tyre  |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |                                                                                     |
| Life remaining             |                                                                                   |                           |                                                                                     |
| LHS Front Tyre             | <45%                                                                              | LHS Rear Tyre             | <55%                                                                                |
| RHS Front Tyre             | <45%                                                                              | RHS Rear Tyre             | <55%                                                                                |
| Spare Tyre                 | <65%                                                                              |                           |                                                                                     |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE