



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 JAC S3**

**LUXURY | 58,814 KM**

VIN: LJ12EKR2XP4724500

## **Car highlights**



### **Good Tyre Condition**

Tyre age less than 2 years



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                       |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|-----------------------|
|  Kilometers       | 58814             |  Specs             | Yes                   |
|  Engine           | 1.6L              |  Option Type       | Fully Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive     |
|  Body Type        | SUV               |  Fuel              | Petrol                |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Silver |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags             |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys                |
|  VIN number     | LJ12EKR2XP4724500 |                                                                                                     |                       |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Comfort & Convenience       |  |                                                                                                                       |  |
|-----------------------------------------------------------------------------------------------------------------|--|-----------------------------------------------------------------------------------------------------------------------|--|
| Climate Control AC           |  | Cruise Control                   |  |
| Rear Armrest with cupholder  |  | Steering Mounted Audio Controls  |  |
| Power Folding Mirrors        |  | Rear Defogger                    |  |
| Central Armrest              |  | Automatic Headlights             |  |
| Steering Column Adjuster     |  |                                                                                                                       |  |



## Exteriors

Fog Light Front



Roof Rails



Running Lights



Rear Bumper Spoiler



Halogen Headlights



## Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Entertainment

Bluetooth Player



Apple Play



Android Auto Play



USB Charging Port



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                              |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door             |  |
|                 |                                                                                   | Panel: Light Scuffing < 50mm |                                                                                     |
| Rear left door  |  | Rear right door              |  |
| Panel: Scuffing |                                                                                   | Panel: Paint Chip-off < 5mm  |                                                                                     |

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|             |                                                                                     |
|-------------|-------------------------------------------------------------------------------------|
| Rear Bumper |  |
|-------------|-------------------------------------------------------------------------------------|

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Pillars Condition

|                            |                                                                                     |                             |                                                                                       |
|----------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|
| Left A Pillar              |  | Right A Pillar              |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |

|                                       |   |                                               |   |
|---------------------------------------|---|-----------------------------------------------|---|
| Right A to B Pillar                   | ✓ | Left B Pillar                                 | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading                    | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar                           | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                                 | ✓ |
| Running Board Condition               |   | Right Running Board                           |   |
| Left Running Board                    | ✓ | Front Right Sill Trim: Low Visual Dent < 50mm | ! |
| Sunroof Glass Condition (If Equipped) |   |                                               |   |
| Sun Roof Glass                        | ✓ |                                               |   |
| Windshield Condition                  |   |                                               |   |
| Front Windshield                      | ✓ | Rear Windshield                               | ✓ |
| Structural Assessment                 |   |                                               |   |
| Chassis Condition                     | ✓ | Apron                                         | ✓ |
| Boot Floor                            | ✓ | Firewall Condition                            | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition                  | ✓ |
| Cowl Top                              |   |                                               |   |
| Cowl Top                              | ✓ |                                               |   |
| Rear View Mirror Condition            |   |                                               |   |
| Left Hand Side Mirror                 | ! | Left Side Mirror                              | ✓ |
| Body: Scuffing                        |   |                                               |   |
| Right Side Mirror                     | ✓ |                                               |   |
| Alloy Wheel/ Rim                      |   |                                               |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim                          | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim                         | ! |
|                                       |   | Rim: Alloy Face/Scuffing                      |   |
| Spare Alloy/ Rim Condition            | ✓ |                                               |   |
| Antenna                               | ✓ | Grill Condition                               | ✓ |
| Monogram                              | ✓ | Window Glass                                  | ✓ |

|                  |   |  |
|------------------|---|--|
| Wiper            | ✓ |  |
| Panel Condition  |   |  |
| Rear Trunk Panel | ✓ |  |

## Engine & Transmission

|                                |   |                      |
|--------------------------------|---|----------------------|
| Engine                         |   |                      |
| Engine Body                    | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓     |
| Radiator Condition             | ✓ | Radiator Coolant ✓   |
| Fuel System                    |   |                      |
| Fuel Tank                      | ✓ |                      |
| Transmission Operation         |   |                      |
| Gear Shifting                  | ✓ | Drive Axle ✓         |
| Transmission Fluid             | ✓ |                      |

## Steering, Suspension & Brakes

|                        |   |                         |
|------------------------|---|-------------------------|
| Steering               |   |                         |
| Steering wheel         | ✓ |                         |
| Brake System           |   |                         |
| Parking Brake          | ✓ | Brake Master Cylinder ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid ✓           |
| Suspension             |   |                         |
| Shock Absorbers        | ✓ |                         |

## Electricals, Controls & Lights

|                      |   |
|----------------------|---|
| Keys                 |   |
| Master Key           |   |
| Button Faded         | ! |
| Door Locks           |   |
| Child Safety Locking | ✓ |
| Dashboard            |   |

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Instrument Panel      | ✓ |                         |   |
| Airbags               |   |                         |   |
| Airbags               | ✓ |                         |   |
| Controls              | ✓ | Cruise Control          | ✓ |
| Infotainment Display  | ✓ | OBD Connector           | ✓ |
| Music System          | ✓ |                         |   |
| Sunroof Operation     |   |                         |   |
| Sunroof               | ✓ |                         |   |
| Camera                | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| License Plate Light   | ✓ | Fog Lights              | ✓ |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC Switch               | ✓ |
| AC System Leaks       | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent   | ✓ | Heater                  | ✓ |
| Rear Blower Switch    | ✓ |                         |   |
| Rear Defogger         | ✓ | USB Charging Port       | ✓ |
| Power/ Manual Windows | ✓ | Memory Seats            | ✓ |

## Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder                     | ✓ | Glove Box       | ✓ |
| Steering Wheel                 | ✓ | Sunvisor        | ✓ |

|                        |   |                      |   |
|------------------------|---|----------------------|---|
| Seat Upholstery        | ✓ | Manual Seat Movement | ✓ |
| Seat Belts             | ✓ | Head Rest            | ✓ |
| Door Controls And Trim | ✓ | Grab Handle          | ✓ |
| Carpet                 | ✓ | Headliner            | ✓ |
| Rear View Mirror       | ✓ | Toolkit              | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <75% | LHS Rear Tyre             | <75% |
| RHS Front Tyre             | <75% | RHS Rear Tyre             | <75% |
| Spare Tyre                 | <55% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE