



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 JAC S3 PLUS**

**LUXURY | 92,835 KM**

VIN: LJ12EKR28P4716007

## **Car highlights**

### **Service History**

Service history available



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**
















Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 92835             |  Specs             | Yes                  |
|  Engine           | 1.6L              |  Option Type       | Fully Loaded         |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | LJ12EKR28P4716007 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                                 |   |
|--|---|---------------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Climate Control AC   |  | Cruise Control                  |  |
| Rear Armrest with cupholder  |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors  |  | Rear Defogger                   |  |
| Central Armrest  |  | Automatic Headlights            |  |
| Steering Column Adjuster   |  |                                 |   |



## Exteriors

Fog Light Front



Roof Rails



Running Lights



Rear Bumper Spoiler



Halogen Headlights



## Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Entertainment

Bluetooth Player



Apple Play



Android Auto Play



USB Charging Port



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |   |  |   |
|-----------------|---|--|---|
| Front left door |  | Front right door<br>Panel: Light Scuffing < 50mm |  |
| Rear left door  |  | Rear right door<br>Panel: Light Scuffing < 50mm  |  |

### Fenders Condition

|  |   |              |   |
|--|---|--------------|---|
| Left Fender<br>Condition: Light Scuffing |  | Right Fender |  |
|--|---|--------------|---|


### Quarter Panels Condition

|                    |  |  |  |
|--------------------|--|--|--|
| Left Quarter Panel |  | Right Quarter Panel<br>Condition: Light Scuffing |  |
|--------------------|--|--|--|

### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|   |   |
|---|---|
| Rear Bumper<br>Rear Bumper: Light Scuffing < 80mm |  |
|---|---|

### Hood Condition

|   |   |
|---|---|
| Hood  |   |
| Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm |  |

### Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

### Pillars Condition

|                                       |   |                              |   |
|---------------------------------------|---|------------------------------|---|
| Left A Pillar                         | ✓ | Right A Pillar               | ✓ |
| Left A to B Pillar Beading            | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar                   | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                | ✓ |
| Running Board Condition               |   |                              |   |
| Left Running Board                    | ✓ | Right Running Board          | ✓ |
| Sunroof Glass Condition (If Equipped) |   |                              |   |
| Sun Roof Glass                        | ✓ |                              |   |
| Windshield Condition                  |   |                              |   |
| Front Windshield                      | ✓ | Rear Windshield              | ✓ |
| Structural Assessment                 |   |                              |   |
| Chassis Condition                     | ✓ | Apron                        | ✓ |
| Boot Floor                            | ✓ | Firewall Condition           | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                              |   |                              |   |
| Cowl Top                              | ✓ |                              |   |
| Rear View Mirror Condition            |   |                              |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror                     | ✓ |                              |   |
| Alloy Wheel/ Rim                      |   |                              |   |
| Left Front Alloy/ Rim                 | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |                              |   |
| Antenna                               | ✓ | Grill Condition              | ! |
|                                       |   | Light Scuffing < 50mm        |   |
| Monogram                              | ✓ | Window Glass                 | ✓ |
| Wiper                                 | ✓ |                              |   |

Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Airbags               | ✓ |                         |   |
| Controls              | ✓ | Cruise Control          | ✓ |
| Infotainment Display  | ✓ | OBD Connector           | ✓ |
| Music System          | ✓ |                         |   |
| Sunroof Operation     |   |                         |   |
| Sunroof               | ✓ |                         |   |
| Camera                | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| License Plate Light   | ✓ | Fog Lights              | ✓ |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC Switch               | ✓ |
| AC System Leaks       | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent   | ✓ | Heater                  | ✓ |
| Rear Defogger         | ✓ | USB Charging Port       | ✓ |
| Power/ Manual Windows | ✓ |                         |   |

## Interiors & Luggage

|  |   |                                     |   |
|--|---|-------------------------------------|---|
| Dashboard And Instrument Panel                                 |   | Central Console                     |   |
| Dashboard Upholstery: Minor Scuffing/<br>Disfiguration/ Melted | ! | Gear Shift Knob: Knob Fair Use Wear | ! |
| Cup Holder   | ✓ | Glove Box                           | ✓ |
| Steering Wheel   |   | Sunvisor                            | ✓ |
| Steering Wheel Fair Use Wear                                   | ! |                                     |   |
| Seat Upholstery  | ✓ | Manual Seat Movement                | ✓ |
| Seat Belts   | ✓ | Head Rest                           | ✓ |



|   |   |             |   |
|---|---|-------------|---|
| Door Controls And Trim                  | ✓ | Grab Handle | ✓ |
| Carpet                                  | ! | Headliner   | ✓ |
| Front Left Floor Mat: Smudge/Burn/Crack |   |             |   |
| Rear View Mirror                        | ✓ | Toolkit     | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <75% | LHS Rear Tyre             | <75% |
| RHS Front Tyre             | <75% | RHS Rear Tyre             | <75% |
| Spare Tyre                 | <65% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE