



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 CHEVROLET CAPTIVA**

**LS | 91,619 KM**

VIN: LZWADAGA4RB010316

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 91619             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 10.2 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 7 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | LZWADAGA4RB010316 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                                     |                                                                                                |                                 |                                                                                                  |
|-------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|---------------------------------|--------------------------------------------------------------------------------------------------|
| <div></div> <div>Exteriors</div>                 |                                                                                                |                                 |                                                                                                  |
| Fog Light Front                                                                                                                     | <div></div> | Roof Rails                      | <div></div> |
| Running Lights                                                                                                                      | <div></div> | Rear Bumper Spoiler             | <div></div> |
| Halogen Headlights                                                                                                                  | <div></div> |                                 |                                                                                                  |
| <div></div> <div>Comfort &amp; Convenience</div> |                                                                                                |                                 |                                                                                                  |
| Cruise Control                                                                                                                      | <div></div> | Steering Mounted Audio Controls | <div></div> |

|                                                                                                                |   |                     |   |
|----------------------------------------------------------------------------------------------------------------|---|---------------------|---|
| Rear Defogger                                                                                                  | ✓ | Central Armrest     | ✓ |
| Steering Column Adjuster                                                                                       | ✓ |                     |   |
|  <b>Safety &amp; Security</b> |   |                     |   |
| Parking Sensors Rear                                                                                           | ✓ | Reverse Camera      | ✓ |
| Traction Control                                                                                               | ✓ | Airbag Driver Front | ✓ |
| ABS                                                                                                            | ✓ | Central Locking     | ✓ |
| Child Safety Locking                                                                                           | ✓ |                     |   |
|  <b>Entertainment</b>         |   |                     |   |
| Bluetooth Player                                                                                               | ✓ | Apple Play          | ✓ |
| Android Auto Play                                                                                              | ✓ | USB Charging Port   | ✓ |
| Infotainment System                                                                                            | ✓ | USB player          | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Right Fender: Low Visual Dent

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



|                             |   |                                               |   |
|-----------------------------|---|-----------------------------------------------|---|
| Right A to B Pillar         | ✓ | Left B Pillar                                 | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading                    | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar<br>Low Visual Dent < 50mm | ! |
| Right B to C Pillar Beading | ✓ | Left C Pillar                                 | ✓ |
| Running Board Condition     |   |                                               |   |
| Left Running Board          | ✓ | Right Running Board                           | ✓ |
| Windshield Condition        |   |                                               |   |
| Front Windshield            | ✓ | Rear Windshield                               | ✓ |
| Structural Assessment       |   |                                               |   |
| Chassis Condition           | ✓ | Apron                                         | ✓ |
| Boot Floor                  | ✓ | Firewall Condition                            | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition                  | ✓ |
| Cowl Top                    |   |                                               |   |
| Cowl Top                    | ✓ |                                               |   |
| Rear View Mirror Condition  |   |                                               |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror                              | ✓ |
| Right Side Mirror           | ✓ |                                               |   |
| Alloy Wheel/ Rim            |   |                                               |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim                          | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim                         | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                                               |   |
| Wheel cover                 | ✓ | Antenna                                       | ✓ |
| Grill Condition             | ✓ | Monogram                                      | ✓ |
| Window Glass                | ✓ | Wiper                                         | ✓ |
| Panel Condition             |   |                                               |   |
| Rear Trunk Panel            | ✓ |                                               |   |



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

|                      |   |                         |   |
|----------------------|---|-------------------------|---|
| Airbags              | ✓ |                         |   |
| Controls             | ✓ | Cruise Control          | ✓ |
| Infotainment Display | ✓ | OBD Connector           | ✓ |
| Music System         | ✓ | Camera                  | ✓ |
| Lights               |   |                         |   |
| Headlight            | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster   | ✓ | Daylight Running Lights | ✓ |
| License Plate Light  | ✓ | Fog Lights              | ✓ |
| Air Conditioning     |   |                         |   |
| AC Cooling           | ✓ | AC Switch               | ✓ |
| AC System Leaks      | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent  | ✓ | Heater                  | ✓ |
| Rear Blower Switch   | ✓ |                         |   |
| Parking Sensors      | ✓ | Rear Defogger           | ✓ |
| USB Charging Port    | ✓ | Power/ Manual Windows   | ✓ |

## Interiors & Luggage

|                                |   |                                                |   |
|--------------------------------|---|------------------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console                                | ✓ |
| Glove Box                      | ✓ | Steering Wheel                                 | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery                                |   |
|                                |   | Rear Right Seat: Leather/ Fabric Fair Use Wear | ⚠ |
| Manual Seat Movement           | ✓ | Seat Belts                                     | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim                         | ✓ |
| Grab Handle                    | ✓ | Carpet                                         | ✓ |
| Headliner                      | ✓ | Rear View Mirror                               | ✓ |



## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<55%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<75%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE