



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 SUZUKI BALENO**

**GLX | 17,239 KM**

VIN: MBHWBAC22RG546045

### Car highlights



#### **Manufacturer warranty**

Till 24/10/2030 (Not verified)



#### **Cruise control**

Cruise control to drive with ease & comfort

#### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



#### **Apple play**

Enjoy your drive with apple play



#### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	17239	 Specs	Yes
 Engine	1.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MBHWBAC22RG546045		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Heads up Display	
Cruise Control	
Power Folding Mirrors	
Central Armrest	
Steering Column Adjuster	
Climate Control AC	
Steering Mounted Audio Controls	
Rear Defogger	
Automatic Headlights	



## Safety & Security

360 degree Camera	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Traction Control	✓
Front Camera	✓	Side Camera	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		



## Exteriors

Fog Light Front	✓	Running Lights	✓
LED Headlights	✓		



## Entertainment

Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent, Chip

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition			
Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

### Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

### Fuel System

Fuel Tank 

### Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

## Steering, Suspension & Brakes

### Steering

Steering wheel 

### Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

### Suspension

Shock Absorbers 

## Electricals, Controls & Lights

### Keys

Master Key  Spare Key(s) 

### Door Locks

Child Safety Locking 

### Dashboard

Instrument Panel 

### Airbags

Airbags 

Controls	✓	Cruise Control	✓
Heads Up Display	✓	Infotainment Display	✓
OBD Connector	✓	Music System	✓
Camera	✓		
<b>Lights</b>			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓	Fog Lights	✓
<b>Air Conditioning</b>			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

## **Interiors & Luggage**

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓

Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<45%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE