



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 JEEP GRAND CHEROKEE L**

**LIMITED | 74,124 KM**

VIN: 1C4RJKBG8P8849623

## **Car highlights**



### **Great condition**

Car has low imperfections



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat, Memory Seats & more

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 74124             |  Specs             | Yes                  |
|  Engine           | 3.6L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive     |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 9.7 km/L mileage     |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 12 Airbags           |
|  Seating Capacity | 7 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | 1C4RJKBG8P8849623 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                       |                                                                                     |                               |                                                                                       |
|-------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------|---------------------------------------------------------------------------------------|
|  Safety & Security |                                                                                     |                               |                                                                                       |
| Adaptive cruise control                                                                               |  | Lane Departure Warning System |  |
| Navigation                                                                                            |  | Parking Sensors Rear          |  |
| Reverse Camera                                                                                        |  | Blind Spot Monitor            |  |
| Traction Control                                                                                      |  | Airbag Curtain Shield         |  |
| Airbag Knees                                                                                          |  | Airbag Driver Front           |  |

|                                                                                                                    |   |                             |   |
|--------------------------------------------------------------------------------------------------------------------|---|-----------------------------|---|
| ABS                                                                                                                | ✓ | Central Locking             | ✓ |
| Child Safety Locking                                                                                               | ✓ |                             |   |
|  <b>Comfort &amp; Convenience</b> |   |                             |   |
| Climate Control AC                                                                                                 | ✓ | Cruise Control              | ✓ |
| Memory Seats                                                                                                       | ✓ | Rear Armrest with cupholder | ✓ |
| Steering Mounted Audio Controls                                                                                    | ✓ | Ventilated Seat             | ✓ |
| Power Tailgate/ Power Trunk                                                                                        | ✓ | Rear Defogger               | ✓ |
| Central Armrest                                                                                                    | ✓ | Remote Engine Start         | ✓ |
| Automatic Headlights                                                                                               | ✓ | Steering Column Adjuster    | ✓ |
|  <b>Exteriors</b>                 |   |                             |   |
| Fog Light Front                                                                                                    | ✓ | Roof Rails                  | ✓ |
| Running Lights                                                                                                     | ✓ | Rear Bumper Spoiler         | ✓ |
| LED Headlights                                                                                                     | ✓ |                             |   |
|  <b>Performance</b>             |   |                             |   |
| Paddle Shift                                                                                                       | ✓ |                             |   |
|  <b>Entertainment</b>           |   |                             |   |
| Bluetooth Player                                                                                                   | ✓ | Apple Play                  | ✓ |
| USB Charging Port                                                                                                  | ✓ | Infotainment System         | ✓ |
| USB player                                                                                                         | ✓ |                             |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                                                       |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|-------------------------------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door<br>Panel: Low Visibility Dent < 30mm |  |
| Rear left door  |  | Rear right door<br>Panel: Low Visual Dent < 30mm      |  |

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                   |                                                   |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------------------------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel<br>Condition: Low Visual Dent |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------------------------------------|-------------------------------------------------------------------------------------|

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|             |                                                                                     |
|-------------|-------------------------------------------------------------------------------------|
| Rear Bumper |  |
|-------------|-------------------------------------------------------------------------------------|

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Pillars Condition

|                            |                                                                                     |                             |                                                                                       |
|----------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|
| Left A Pillar              |  | Right A Pillar              |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |

|                                       |   |                              |   |
|---------------------------------------|---|------------------------------|---|
| Right A to B Pillar                   | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                | ✓ |
| Running Board Condition               |   |                              |   |
| Left Running Board                    | ✓ | Right Running Board          | ✓ |
| Sunroof Glass Condition (If Equipped) |   |                              |   |
| Sun Roof Glass                        | ✓ |                              |   |
| Windshield Condition                  |   |                              |   |
| Front Windshield                      | ✓ | Rear Windshield              | ✓ |
| Structural Assessment                 |   |                              |   |
| Chassis Condition                     | ✓ | Apron                        | ✓ |
| Boot Floor                            | ✓ | Firewall Condition           | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                              |   |                              |   |
| Cowl Top                              | ✓ |                              |   |
| Rear View Mirror Condition            |   |                              |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror                     | ✓ |                              |   |
| Alloy Wheel/ Rim                      |   |                              |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |                              |   |
| Antenna                               | ✓ | Grill Condition              | ✓ |
| Monogram                              | ✓ | Window Glass                 | ✓ |
| Wiper                                 | ✓ |                              |   |
| Panel Condition                       |   |                              |   |

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Airbags               | ✓ |                         |   |
| Controls              | ✓ | Cruise Control          | ✓ |
| Infotainment Display  | ✓ | OBD Connector           | ✓ |
| Radar (If Equipped)   | ✓ | Navigation System       | ✓ |
| Music System          | ✓ |                         |   |
| Sunroof Operation     |   |                         |   |
| Sunroof               | ✓ |                         |   |
| Camera                | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| License Plate Light   | ✓ |                         |   |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC Switch               | ✓ |
| AC System Leaks       | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent   | ✓ | Heater                  | ✓ |
| Rear Blower Switch    | ✓ |                         |   |
| Rear Defogger         | ✓ | USB Charging Port       | ✓ |
| Power/ Manual Windows | ✓ | Seat Heaters            | ✓ |
| Memory Seats          | ✓ |                         |   |

---

## Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder                     | ✓ | Glove Box       | ✓ |
| Steering Wheel                 | ✓ | Sunvisor        | ✓ |

|                        |   |                      |   |
|------------------------|---|----------------------|---|
| Seat Upholstery        | ✓ | Manual Seat Movement | ✓ |
| Seat Belts             | ✓ | Head Rest            | ✓ |
| Door Controls And Trim | ✓ | Grab Handle          | ✓ |
| Carpet                 | ✓ | Headliner            | ✓ |
| Rear View Mirror       | ✓ | Toolkit              | ✓ |

## Tyres

Tyres Condition

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <45% | LHS Rear Tyre             | <55% |
| RHS Front Tyre             | <55% | RHS Rear Tyre             | <55% |
| Spare Tyre                 | <75% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE