



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 TOYOTA YARIS

E | 50,184 KM

VIN: MR2BF9C31R0042250

## Car highlights

### Fuel Efficient

Fuel efficient with 19.0 km/L



### Great Parking Assistance

Reverse Camera, Parking Sensors Rear

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play















Enjoy your drive with apple play



### Amazing Comfort










Power driver seat



## Basic Details

 Kilometers	<b>50184</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	Fuel Efficiency	<b>19.0 km/L mileage</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MR2BF9C31R0042250</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 <b>Comfort &amp; Convenience</b>			

Steering Mounted Audio Controls		Rear Defogger	
Central Armrest		Steering Column Adjuster	
 <b>Entertainment</b>			
Bluetooth Player		Apple Play	
Android Auto Play		Infotainment System	
USB player			
 <b>Exteriors</b>			
LED Headlights			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Low Visibility  
Dent < 30mm



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Light  
Scuffing < 50mm



### Fenders Condition

Left Fender

Condition: Low Visual Dent, Light Scuffing



Right Fender

Right Fender: Light Scuffing



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Light Scuffing



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood



### Trunk Condition

Trunk



Trunk condition

Trunk



### Roof Condition

Roof



### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition			
Light Scuffing < 50mm	⚠	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls	✓	Infotainment Display	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	!
		De Silvered Mirror<10%	
Toolkit	✓		



## Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



## Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<75%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<65%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE