



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 MAZDA CX 3

GT | 60,832 KM

VIN: MM7DKBW77RW706182

## Car highlights



### Good Tyre Condition

Tyre age less than 2 years



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 60832             |  Specs             | Yes                  |
|  Engine           | 2.0L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Ashen |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | MM7DKBW77RW706182 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                 |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                 |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                  |  |
| Rear Armrest with cupholder                                                                                          |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors                                                                                                |  | Rear Defogger                   |  |
| Central Armrest                                                                                                      |  | Automatic Headlights            |  |
| Steering Column Adjuster                                                                                             |  |                                 |                                                                                       |



## Safety & Security

Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Exteriors

Running Lights



Halogen Headlights



## Entertainment

Bluetooth Player



Apple Play



Android Auto Play



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                                                                         |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door<br>Panel: Light Scuffing < 50mm                        |  |
| Rear left door  |  | Rear right door<br>Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm |  |

### Fenders Condition

|                                          |                                                                                   |              |                                                                                     |
|------------------------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender<br>Condition: Light Scuffing |  | Right Fender |  |
|------------------------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                     |                                                   |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------------------------------------|---------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel<br>Condition: Low Visual Dent |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------------------------------------|---------------------------------------------------------------------------------------|

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                                   |                                                                                     |
|---------------------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper<br>Rear Bumper: Light Scuffing < 80mm |  |
|---------------------------------------------------|-------------------------------------------------------------------------------------|

### Hood Condition

|                                       |                                                                                     |
|---------------------------------------|-------------------------------------------------------------------------------------|
| Hood<br>Bonnet: Light Scuffing < 50mm |  |
|---------------------------------------|-------------------------------------------------------------------------------------|

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Pillars Condition

|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Left A Pillar               | ✓ | Right A Pillar               | ✓ |
| Left A to B Pillar Beading  | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             |   |                              |   |
| Light Scuffing < 50mm       | ! | Monogram                     | ✓ |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |

|                  |   |  |  |
|------------------|---|--|--|
| Rear Trunk Panel | ✓ |  |  |
|------------------|---|--|--|

---

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Fuel System                    |   |                    |   |
| Fuel Tank                      | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| Transmission Fluid             | ✓ |                    |   |

---

## Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Suspension             |   |                       |   |
| Shock Absorbers        | ✓ |                       |   |

---

## Electricals, Controls & Lights

|                      |   |              |   |
|----------------------|---|--------------|---|
| Keys                 |   |              |   |
| Master Key           | ✓ | Spare Key(s) | ✓ |
| Door Locks           |   |              |   |
| Child Safety Locking | ✓ |              |   |
| Dashboard            |   |              |   |
| Instrument Panel     | ✓ |              |   |
| Airbags              |   |              |   |

|                                        |   |                         |   |
|----------------------------------------|---|-------------------------|---|
| Airbags                                | ✓ |                         |   |
| Controls                               | ✓ | Cruise Control          | ✓ |
| Infotainment Display                   | ✓ | OBD Connector           | ✓ |
| Navigation System                      | ! | Music System            | ✓ |
| Condition: Available - SD Card Missing |   |                         |   |
| Camera                                 | ✓ |                         |   |
| Lights                                 |   |                         |   |
| Headlight                              | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster                     | ✓ | Daylight Running Lights | ✓ |
| License Plate Light                    | ✓ |                         |   |
| Air Conditioning                       |   |                         |   |
| AC Cooling                             | ✓ | AC Switch               | ✓ |
| AC System Leaks                        | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent                    | ✓ | Heater                  | ✓ |
| Rear Defogger                          | ✓ | USB Charging Port       | ✓ |
| Power/ Manual Windows                  | ✓ |                         |   |

## Interiors & Luggage

|                                |   |                                     |   |
|--------------------------------|---|-------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console                     | ! |
|                                |   | Gear Shift Knob: Knob Fair Use Wear |   |
| Cup Holder                     | ✓ | Glove Box                           | ✓ |
| Steering Wheel                 | ! | Sunvisor                            | ✓ |
| Steering Wheel Fair Use Wear   |   |                                     |   |
| Seat Upholstery                | ✓ | Manual Seat Movement                | ✓ |
| Seat Belts                     | ✓ | Head Rest                           | ✓ |
| Door Controls And Trim         | ✓ | Grab Handle                         | ✓ |

|                  |   |           |   |
|------------------|---|-----------|---|
| Carpet           | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit   | ✓ |

## Tyres

Tyres Condition

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <55% | LHS Rear Tyre             | <65% |
| RHS Front Tyre             | <55% | RHS Rear Tyre             | <45% |
| Spare Tyre                 | <65% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE