



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2018 KIA SPORTAGE**

**EX | 118,432 KM**

VIN: U5YPH8140JL320896

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Music System**

Enjoy your drive with music system



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                    |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|--------------------|
|  Kilometers       | 118432            |  Specs             | Yes                |
|  Engine           | 1.6L              |  Option Type       | Fully Loaded       |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive  |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 12.7 km/L mileage  |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Red |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags          |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys             |
|  VIN number     | U5YPH8140JL320896 |                                                                                                     |                    |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                                        |  |                                                                                                |                |                                                                                                  |
|----------------------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------|----------------|--------------------------------------------------------------------------------------------------|
| <div> <b>Comfort &amp; Convenience</b></div>        |  |                                                                                                |                |                                                                                                  |
| Panoramic Sunroof                                                                                                                      |  | <div></div> | Cruise Control | <div></div> |
| Steering Mounted Audio Controls                                                                                                        |  | <div></div> |                |                                                                                                  |
| <div><div></div> <b>Exteriors</b></div>             |  |                                                                                                |                |                                                                                                  |
| Fog Light Front                                                                                                                        |  | <div></div> |                |                                                                                                  |
| <div><div></div> <b>Safety &amp; Security</b></div> |  |                                                                                                |                |                                                                                                  |

|                                                                                                        |                                                                                                         |
|--------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|
|                                                                                                        |                                                                                                         |
| Parking Sensors Front  | Parking Sensors Rear  |
| Reverse Camera        |                                                                                                         |
|  <b>Entertainment</b> |                                                                                                         |
| USB Charging Port     | Infotainment System  |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                                                                                               |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door<br>Panel: Light Scuffing < 50mm                                              |  |
| Rear left door  |  | Rear right door<br>Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm |  |

### Fenders Condition

|                                          |                                                                                   |                                                               |                                                                                     |
|------------------------------------------|-----------------------------------------------------------------------------------|---------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Left Fender<br>Condition: Light Scuffing |  | Right Fender<br>Right Fender: Low Visual Dent, Light Scuffing |  |
|------------------------------------------|-----------------------------------------------------------------------------------|---------------------------------------------------------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                     |                                                                   |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel<br>Condition: Low Visual Dent, Light Scuffing |  |
|--------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------|---------------------------------------------------------------------------------------|

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                                              |                                                                                     |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper<br>Rear Bumper: Light Scuffing < 80mm, Chip< 8mm |  |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------|

### Hood Condition

|                                       |                                                                                     |
|---------------------------------------|-------------------------------------------------------------------------------------|
| Hood<br>Bonnet: Light Scuffing < 50mm |  |
|---------------------------------------|-------------------------------------------------------------------------------------|

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Pillars Condition

|                                                                                      |   |                              |   |
|--------------------------------------------------------------------------------------|---|------------------------------|---|
| Left A Pillar                                                                        | ✓ | Right A Pillar               | ✓ |
| Left A to B Pillar Beading                                                           | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar                                                                  | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim                                                                   | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim                                                                  | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading                                                          | ✓ | Left C Pillar                | ✓ |
| Running Board Condition                                                              |   |                              |   |
| Left Running Board                                                                   | ✓ | Right Running Board          | ✓ |
| Sunroof Glass Condition (If Equipped)                                                |   |                              |   |
| Sun Roof Glass                                                                       | ✓ |                              |   |
| Windshield Condition                                                                 |   |                              |   |
| Front Windshield                                                                     |   |                              |   |
| Condition: Driver Side/Stone Chip<br>Mark<5mm, Passenger Side/Stone Chip<br>Mark<8mm | ! | Rear Windshield              | ✓ |
| Structural Assessment                                                                |   |                              |   |
| Chassis Condition                                                                    | ✓ | Apron                        | ✓ |
| Boot Floor                                                                           | ✓ | Firewall Condition           | ✓ |
| Cowl Top                                                                             | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                                                                             |   |                              |   |
| Cowl Top                                                                             | ✓ |                              |   |
| Rear View Mirror Condition                                                           |   |                              |   |
| Left Hand Side Mirror                                                                | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror                                                                    | ✓ |                              |   |
| Alloy Wheel/ Rim                                                                     |   |                              |   |
| Left Front Alloy/ Rim                                                                | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim                                                               | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition                                                           | ✓ |                              |   |
| Antenna                                                                              | ✓ | Grill Condition              | ! |
|                                                                                      |   | Light Scuffing < 50mm        |   |

|                  |   |              |   |
|------------------|---|--------------|---|
| Monogram         | ✓ | Window Glass | ✓ |
| Wiper            | ✓ |              |   |
| Panel Condition  |   |              |   |
| Rear Trunk Panel | ✓ |              |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Fuel System                    |   |                    |   |
| Fuel Tank                      | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| Transmission Fluid             | ✓ |                    |   |

## Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Suspension             |   |                       |   |
| Shock Absorbers        | ✓ |                       |   |

## Electricals, Controls & Lights

|                      |   |              |   |
|----------------------|---|--------------|---|
| Keys                 |   |              |   |
| Master Key           | ✓ | Spare Key(s) | ✓ |
| Door Locks           |   |              |   |
| Child Safety Locking | ✓ |              |   |

|                         |   |                         |   |
|-------------------------|---|-------------------------|---|
| Dashboard               |   |                         |   |
| Instrument Panel        | ✓ |                         |   |
| Airbags                 |   |                         |   |
| Airbags                 | ✓ |                         |   |
| Controls                | ✓ | Cruise Control          | ✓ |
| Infotainment Display    | ✓ | OBD Connector           | ✓ |
| Music System            | ✓ |                         |   |
| Sunroof Operation       |   |                         |   |
| Sunroof                 | ✓ |                         |   |
| Camera                  | ✓ |                         |   |
| Lights                  |   |                         |   |
| Headlight               | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster      | ✓ | Daylight Running Lights | ✓ |
| License Plate Light     | ✓ | Fog Lights              | ✓ |
| Air Conditioning        |   |                         |   |
| AC Cooling              | ✓ | AC Switch               | ✓ |
| AC System Leaks         | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent     | ✓ | Heater                  | ✓ |
| Rear Blower Switch      | ✓ |                         |   |
| Rear Defogger           | ! | USB Charging Port       | ✓ |
| Extensive Wear Of Strip |   |                         |   |
| Power/ Manual Windows   | ✓ |                         |   |



## Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder                     | ✓ | Glove Box       | ✓ |



|                                                                               |   |                      |   |
|-------------------------------------------------------------------------------|---|----------------------|---|
| Steering Wheel<br>Color Faded                                                 | ⚠ | Sunvisor             | ✓ |
| Seat Upholstery<br>Driver Seat: Minor Leather/ Fabric Fair Use<br>Wear/ Tears | ⚠ | Manual Seat Movement | ✓ |
| Seat Belts                                                                    | ✓ | Head Rest            | ✓ |
| Door Controls And Trim                                                        | ✓ | Grab Handle          | ✓ |
| Carpet                                                                        | ✓ | Headliner            | ✓ |
| Rear View Mirror                                                              | ✓ | Toolkit              | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <75% | LHS Rear Tyre             | <75% |
| RHS Front Tyre             | <65% | RHS Rear Tyre             | <75% |
| Spare Tyre                 | <85% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE