



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 KIA SORENTO

EX | 90,470 KM

VIN: KNARH81D7N5145723

## Car highlights



### Great condition

Car has low imperfections



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Android Auto

Enjoy your drive with Android Auto



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>90470</b>	 Specs	<b>Yes</b>
 Engine	<b>2.5L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel Efficiency	<b>10.9 km/L mileage</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>7 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>KNARH81D7N5145723</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Rear Defogger	
Remote Engine Start	
Cruise Control	
Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk	
Central Armrest	
Automatic Headlights	

Steering Column Adjuster 

 **Exteriors**

Fog Light Front 	Roof Rails 
Running Lights 	Rear Bumper Spoiler 
LED Headlights 	

 **Safety & Security**

Parking Sensors Front 	Parking Sensors Rear 
Reverse Camera 	Traction Control 
Airbag Curtain Shield 	Airbag Driver Front 
ABS 	Central Locking 
Child Safety Locking 	

 **Performance**

Hill Descent Control 	
--	--

 **Entertainment**

Bluetooth Player 	Android Auto Play 
USB Charging Port 	Infotainment System 
USB player 	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Panel: Paint Defect

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield			
Condition: Passenger Side/Stone Chip	!	Rear Windshield	✓
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags			
Controls		Cruise Control	
Infotainment Display		OBD Connector	
Music System			
Sunroof Operation			
Sunroof			
Camera			
Lights			
Headlight		Interior Lights	
Tail Light Cluster		Daylight Running Lights Right DRL: Low Brightness	
License Plate Light		Fog Lights	
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Rear Blower Switch			
Rear Defogger		USB Charging Port	
Power/ Manual Windows			

## **Interiors & Luggage**

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	

Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<85%

RHS Front Tyre

<75%

RHS Rear Tyre

<85%

Spare Tyre

<55%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE