



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 NISSAN X TRAIL

S | 57,117 KM

VIN: JN1BT2MU0MW020456

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

| | | | |
|--|--------------------------|---|----------------------------|
|  Kilometers | 57117 |  Specs | Yes |
|  Engine | 2.5L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Grey |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 1 Keys |
|  VIN number | JN1BT2MU0MW020456 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Comfort & Convenience | | | |
|--|---|-----------------------------|---|
| Cruise Control |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls |  | Rear Defogger |  |
| Central Armrest |  | Steering Column Adjuster |  |
|  Exteriors | | | |
| Running Lights |  | Rear Bumper Spoiler |  |

Halogen Headlights



Safety & Security

Reverse Camera



Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light



Scuffing < 50mm

Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender



Right Fender

Condition: Low Visual Dent



Right Fender: Low Visual Dent

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Trim: Light Scuffing < 80mm



Condition: Low Visual Dent

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Chip<

8mm

Hood Condition

Hood



Bonnet: Low Visibility Dent < 30mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

| | | | |
|-----------------------------|--|-----------------------------|--|
| Left A Pillar | | Right A Pillar | |
| Left A to B Pillar Beading | | Right A to B Pillar Beading | |
| Right A to B Pillar | | Left B Pillar | |
| Left B Pillar Trim | | Left B to C Pillar Beading | |
| Right C Pillar Trim | | Right B to C Pillar | |
| Right B to C Pillar Beading | | Left C Pillar | |

Running Board Condition

| | | | |
|--------------------|--|----------------------------------|--|
| Left Running Board | | Right Running Board | |
| | | Condition: Light Scuffing < 80mm | |

Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip
Mark<5mm, Passenger Side/Stone Chip
Mark<8mm



Rear Windshield



Structural Assessment

| | | | |
|-------------------------|--|------------------------------|--|
| Chassis Condition | | Apron | |
| Boot Floor | | Firewall Condition | |
| Cowl Top | | Head Light Support Condition | |
| Cowl Top | | | |
| Cowl Top | | | |
| Fair Use Wear/Crack<5mm | | | |

Rear View Mirror Condition

| | | | |
|-----------------------|--|------------------|--|
| Left Hand Side Mirror | | Left Side Mirror | |
| Right Side Mirror | | | |

Alloy Wheel/ Rim

| | | | |
|----------------------------|--|-----------------------|--|
| Left Front Alloy/ Rim | | Left Rear Alloy/ Rim | |
| Right Front Alloy/ Rim | | Right Rear Alloy/ Rim | |
| Spare Alloy/ Rim Condition | | | |
| Wheel cover | | Antenna | |

Grill Condition
Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls 

Cruise Control 

Infotainment Display 

OBD Connector 

Music System

Steering Mounted Audio Controls: Not Working Properly 

Camera 

Lights

Headlight 

Interior Lights 

Tail Light Cluster 

Daylight Running Lights 

License Plate Light 

Air Conditioning

AC Cooling 

AC Switch 

AC System Leaks 

Center AC Vent 

Front Right AC Vent 

Heater 

Rear Blower Switch 

Rear Defogger 

USB Charging Port 

Power/ Manual Windows 

Interiors & Luggage

Dashboard And Instrument Panel 

Central Console 

Cup Holder 

Glove Box 

Steering Wheel 

Sunvisor 

Seat Upholstery 

Manual Seat Movement 

| | | | |
|-------------------------|---|---|---|
| Seat Belts | ! | Head Rest | ✓ |
| Rear Right Seat: Smudge | | | |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ! |
| | | Jack Availability: Toe Hook Not Available | |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <85% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <85% |
| Spare Tyre | <85% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE