



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 SUZUKI CIAZ

GL | 87,620 KM

VIN: MA3VC7A11RA493849

## Car highlights



### Great condition

Car has low imperfections



### Great Parking Assistance

Reverse Camera

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

|  |                          |   |                             |
|--|--------------------------|---|-----------------------------|
|  Kilometers       | <b>87620</b>             |  Specs             | <b>Yes</b>                  |
|  Engine           | <b>1.5L</b>              |  Option Type       | <b>Basic</b>                |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>Front Wheel Drive</b>    |
|  Body Type        | <b>SEDAN</b>             | Fuel Efficiency   | <b>16.7 km/L mileage</b>    |
|  Wheel Type       | <b>Steel Wheels</b>      |  Exterior Color    | <b>Exterior Color White</b> |
|  Interior Trim    | <b>Fabric Trim</b>       |  Number of Airbags | <b>2 Airbags</b>            |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>2 Keys</b>               |
|  VIN number      | <b>MA3VC7A11RA493849</b> |   |                             |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  <b>Comfort &amp; Convenience</b> |   |
|--|---|
| Rear Armrest with cupholder       | Steering Mounted Audio Controls  |
| Rear Defogger                     | Central Armrest                  |
| Steering Column Adjuster          |   |
|  <b>Entertainment</b>             |   |
| Rear Seat Entertainment           | Bluetooth Player                 |

|  |   |                      |   |
|--|---|----------------------|---|
| Infotainment System  |   | USB player           |   |
|  <b>Safety &amp; Security</b> |   |                      |   |
| Reverse Camera   |  | Traction Control     |  |
| Airbag Driver Front  |  | ABS                  |  |
| Central Locking  |  | Child Safety Locking |  |
|  <b>Exteriors</b>             |   |                      |   |
| Halogen Headlights   |  |                      |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door



Rear left door



Rear right door



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper



### Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm



### Trunk Condition

Trunk



### Trunk condition

Trunk



### Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Antenna                     | ✓ | Grill Condition              | ✓ |
| Monogram                    | ✓ | Window Glass                 | ✓ |
| Wiper                       | ✓ |                              |   |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |

---

## Engine & Transmission

|             |   |                    |   |
|-------------|---|--------------------|---|
| Engine      |   |                    |   |
| Engine Body | ✓ | Engine Performance | ✓ |

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition | ✓ |
| Radiator Coolant               | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Tank                      | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| Transmission Fluid             | ✓ |                    |   |

### **Steering, Suspension & Brakes**

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Suspension             |   |                       |   |
| Shock Absorbers        | ✓ |                       |   |

### **Electricals, Controls & Lights**

|                      |   |                      |   |
|----------------------|---|----------------------|---|
| Keys                 |   |                      |   |
| Master Key           | ✓ | Spare Key(s)         | ✓ |
| Door Locks           |   |                      |   |
| Child Safety Locking | ✓ |                      |   |
| Dashboard            |   |                      |   |
| Instrument Panel     | ✓ |                      |   |
| Airbags              |   |                      |   |
| Airbags              | ✓ |                      |   |
| Controls             | ✓ | Infotainment Display | ✓ |
| OBD Connector        | ✓ | Music System         | ✓ |

## Sunroof Operation

Sunroof



## Lights

Headlight

Left: Low Brightness lamps



Interior Lights



Tail Light Cluster



License Plate Light



## Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<55%

RHS Front Tyre

<65%

RHS Rear Tyre

<45%

Spare Tyre

<75%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE