



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 INFINITI QX70

LUXURY | 110,979 KM

VIN: JNRCS1MW1JM710174

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth















Enjoy your drive with bluetooth



Amazing Comfort












Power driver seat, Memory Seats & more




Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 110979 |  Specs | Yes |
|  Engine | 3.7L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | All Wheel Drive |
|  Body Type | SUV | Fuel Efficiency | 8.1 km/L mileage |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Black |
|  Interior Trim | Leather Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | JNRCS1MW1JM710174 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Safety & Security | | | |
|---|--|--|--|
| 360 degree Camera  | | Navigation  | |
| Parking Sensors Front  | | Parking Sensors Rear  | |
| Reverse Camera  | | Traction Control  | |
| Front Camera  | | Side Camera  | |
| Airbag Curtain Shield  | | Airbag Driver Front  | |

| | | | |
|--|---|-----------------------------|---|
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |
|  Comfort & Convenience | | | |
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Memory Seats | ✓ | Rear Armrest with cupholder | ✓ |
| Steering Mounted Audio Controls | ✓ | Power Folding Mirrors | ✓ |
| Ventilated Seat | ✓ | Power Tailgate/ Power Trunk | ✓ |
| Rear Defogger | ✓ | Central Armrest | ✓ |
| Automatic Headlights | ✓ | Steering Column Adjuster | ✓ |
|  Exteriors | | | |
| Fog Light Front | ✓ | Roof Rails | ✓ |
| Running Lights | ✓ | Rear Bumper Spoiler | ✓ |
| HID Headlights | ✓ | | |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|--|---|
| Front left door |  | Front right door Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm |  |
|-----------------|---|--|---|

| | | | |
|----------------|---|---|---|
| Rear left door |  | Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm |  |
|----------------|---|---|---|

Fenders Condition

| | | | |
|-------------|---|--------------|---|
| Left Fender |  | Right Fender |  |
|-------------|---|--------------|---|


Quarter Panels Condition

| | | | |
|--------------------|---|---------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|---|---------------------|---|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|------------------------------------|---|
| Rear Bumper |  |
| Rear Bumper: Light Scuffing < 80mm | |

Hood Condition

| | |
|------|---|
| Hood |  |
|------|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|---------------|---|----------------|---|
| Left A Pillar |  | Right A Pillar |  |
|---------------|---|----------------|---|

| | | | |
|--|---|--|---|
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield Condition: Scuffing>50mm | ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Antenna | ✓ | Grill Condition Light Scuffing < 50mm | ! |
| Monogram | ✓ | Window Glass | ✓ |

| | |
|------------------|---|
| Wiper | ✓ |
| Panel Condition | |
| Rear Trunk Panel | ✓ |

Engine & Transmission

| | | |
|--------------------------------|---|----------------------|
| Engine | | |
| Engine Body | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓ |
| Radiator Condition | ✓ | Radiator Coolant ✓ |
| Fuel System | | |
| Fuel Tank | ✓ | |
| Transmission Operation | | |
| Gear Shifting | ✓ | Drive Axle ✓ |
| 4*4 Condition (If Applicable) | ✓ | Transmission Fluid ✓ |

Steering, Suspension & Brakes

| | | |
|------------------------|---|-------------------------|
| Steering | | |
| Steering wheel | ✓ | |
| Brake System | | |
| Parking Brake | ✓ | Brake Master Cylinder ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid ✓ |
| Suspension | | |
| Shock Absorbers | ✓ | |

Electricals, Controls & Lights

| | | |
|----------------------|---|----------------|
| Keys | | |
| Master Key | ✓ | Spare Key(s) ✓ |
| Door Locks | | |
| Child Safety Locking | ✓ | |
| Dashboard | | |

| | | | |
|-----------------------|---|-------------------------|---|
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Music System | ✓ | | |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | Seat Heaters | ✓ |
| Memory Seats | ✓ | | |



Interiors & Luggage

| | | | |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |

Steering Wheel
Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<85%

LHS Rear Tyre

<65%

RHS Front Tyre

<85%

RHS Rear Tyre

<65%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE