



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 GEELY MONJARO

GF+ | 68,031 KM

VIN: LB3KX2S15RS006535

## Car highlights



### Panoramic Roof

This car has a panoramic roof



### Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat, Memory Seats & more

## Basic Details

 Kilometers	<b>68031</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Four Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>8 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>LB3KX2S15RS006535</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Heads up Display	
Cruise Control	
Rear Armrest with cupholder	
Power Folding Mirrors	
Power Tailgate/ Power Trunk	
Climate Control AC	
Memory Seats	
Steering Mounted Audio Controls	
Ventilated Seat	
Rear Defogger	

Central Armrest	✓	Remote Engine Start	✓
Automatic Headlights	✓	Steering Column Adjuster	✓



### Safety & Security

Adaptive cruise control	✓	360 degree Camera	✓
Lane Departure Warning System	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Collision Warning System	✓
Traction Control	✓	Front Camera	✓
Side Camera	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓



### Exteriors

Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓	LED Headlights	✓



### Entertainment

Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Right Fender: Light Scuffing

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Bonnet: Light Scuffing < 50mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar	✓	Left B Pillar	✓		
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓		
Right C Pillar Trim	✓	Right B to C Pillar	✓		
Right B to C Pillar Beading	✓	Left C Pillar	✓		
Running Board Condition					
Left Running Board	✓	Right Running Board			
		Rear Right Sill Trim: Light Scuffing < 80mm			
!					
Sunroof Glass Condition (If Equipped)					
Sun Roof Glass	✓				
Windshield Condition					
Front Windshield	✓	Rear Windshield	✓		
Structural Assessment					
Chassis Condition	✓	Apron	✓		
Boot Floor	✓	Firewall Condition	✓		
Cowl Top	✓	Head Light Support Condition	✓		
Cowl Top					
Cowl Top	✓				
Rear View Mirror Condition					
Left Hand Side Mirror	✓	Left Side Mirror	✓		
Right Side Mirror	✓				
Alloy Wheel/ Rim					
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓		
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓		
Spare Alloy/ Rim Condition	✓				
Antenna	✓	Grill Condition	✓		
Monogram	✓	Window Glass	✓		
Wiper	✓				
Panel Condition					

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags		
Airbags	✓	
Controls	✓	Cruise Control
Heads Up Display	✓	Infotainment Display
OBD Connector	✓	Radar (If Equipped)
Music System	✓	
Sunroof Operation		
Sunroof	✓	
Camera	✓	
Lights		
Headlight	✓	Interior Lights
Tail Light Cluster	✓	Daylight Running Lights
License Plate Light	✓	
Air Conditioning		
AC Cooling	✓	AC Switch
AC System Leaks	✓	Center AC Vent
Front Right AC Vent	✓	Heater
Rear Blower Switch	✓	
Rear Defogger	✓	USB Charging Port
Power/ Manual Windows	✓	Memory Seats

## **Interiors & Luggage**

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓

Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Front Left Floor Mat: Smudge/Burn/Crack			
Rear View Mirror		Toolkit	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE