



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 HONDA CIVIC**

**EXI | 105,498 KM**

**VIN: 19XFC2676KE450473**

## **Car highlights**



### **Sunroof**

This car has a sunroof



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	<b>105498</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel Efficiency	<b>16.2 km/L mileage</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Blue</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>19XFC2676KE450473</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Rear Armrest with cupholder	
Rear Defogger	
Remote Engine Start	
 <b>Exteriors</b>	

Fog Light Front		Running Lights	
Halogen Headlights			



### Safety & Security

Parking Sensors Rear		Reverse Camera	
Traction Control		Side Camera	
Airbag Curtain Shield		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			



### Entertainment

Bluetooth Player		Apple Play	
Android Auto Play		USB Charging Port	
Infotainment System		USB player	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Handle: Paint Chip-off < 5mm

Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Chip, Low Visual Dent

Front Bumper Condition

Front Bumper



Condition: Fair Use Wear

Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm, Low Visibility

Dent < 30mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
		Condition: Light Scuffing < 80mm	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Antenna		Grill Condition	
Monogram		Window Glass	
Wiper			

## Panel Condition

Rear Trunk Panel



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



### Door Locks

Child Safety Locking



### Dashboard

Instrument Panel



### Airbags

Airbags			
Controls		Cruise Control	
Infotainment Display		OBD Connector	
Music System			
Sunroof Operation			
Sunroof			
Camera			
Lights			
Headlight		Interior Lights	
Tail Light Cluster		Daylight Running Lights	
License Plate Light		Fog Lights	
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Rear Blower Switch			
Rear Defogger		USB Charging Port	
Power/ Manual Windows			

## **Interiors & Luggage**

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	

Door Controls And Trim



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<65%

RHS Rear Tyre

<75%

Spare Tyre

<65%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE