



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 BMW 520i

JOY EDITION | 24,528 KM

VIN: WBA71AG08PCN23862

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat, Memory Seats

Basic Details

 Kilometers	24528	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WBA71AG08PCN23862		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Memory Seats	
Steering Mounted Audio Controls	
Rear Defogger	
Automatic Headlights	
Cruise Control	
Rear Armrest with cupholder	
Power Folding Mirrors	
Central Armrest	
Steering Column Adjuster	



Safety & Security

Lane Departure Warning System	✓	Navigation	✓
Parking Sensors Front	✓	Parking Sensors Rear	✓
Auto Park Assist	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Collision Warning System	✓
Traction Control	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓



Performance

Paddle Shift	✓	
--------------	---	--



Exteriors

Running Lights	✓	LED Headlights	✓
----------------	---	----------------	---



Entertainment

Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Trim: Crack/Fair Use Wear

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing !
< 50mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Wheel cover	✓	Antenna	✓
Grill Condition			
Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Turbocharger/ Supercharger		Radiator Condition	
Radiator Coolant			
Fuel System			
Fuel Tank			
Transmission Operation			
Gear Shifting		Gear shift	
Drive Axle		Transmission Fluid	

Steering, Suspension & Brakes

Steering

Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Suspension			
Shock Absorbers			

Electricals, Controls & Lights

Keys

Master Key		Spare Key(s)	
Door Locks			
Child Safety Locking			
Dashboard			
Instrument Panel			
Airbags			
Airbags			

Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Radar (If Equipped)	✓	Navigation System	✓
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓

Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<55%

RHS Front Tyre

<65%

RHS Rear Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE