



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 TOYOTA COROLLA CROSS

XL | 94,251 KM

VIN: RKLKUBAG7R0503996

## Car highlights



### Cruise control

Cruise control to drive with ease & comfort



### Great Parking Assistance

Parking Sensors Rear

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

## Basic Details

|  |                          |   |                             |
|--|--------------------------|---|-----------------------------|
|  Kilometers       | <b>94251</b>             |  Specs             | <b>Yes</b>                  |
|  Engine           | <b>1.8L</b>              |  Option Type       | <b>Basic</b>                |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>Front Wheel Drive</b>    |
|  Body Type        | <b>SUV</b>               |  Fuel              | <b>Petrol</b>               |
|  Wheel Type       | <b>Steel Wheels</b>      |  Exterior Color    | <b>Exterior Color White</b> |
|  Interior Trim    | <b>Fabric Trim</b>       |  Number of Airbags | <b>2 Airbags</b>            |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>2 Keys</b>               |
|  VIN number      | <b>RKLKUBAG7R0503996</b> |   |                             |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  <b>Comfort &amp; Convenience</b> |   |                             |   |
|--|---|-----------------------------|---|
| Cruise Control   |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls  |  | Power Folding Mirrors       |  |
| Rear Defogger  |  | Central Armrest             |  |
| Automatic Headlights   |  | Steering Column Adjuster    |  |
|  <b>Safety &amp; Security</b>     |   |                             |   |

|                      |   |                      |   |
|----------------------|---|----------------------|---|
| Parking Sensors Rear | ✓ | Traction Control     | ✓ |
| Airbag Driver Front  | ✓ | ABS                  | ✓ |
| Central Locking      | ✓ | Child Safety Locking | ✓ |



### Exteriors

|                |   |                    |   |
|----------------|---|--------------------|---|
| Running Lights | ✓ | Halogen Headlights | ✓ |
|----------------|---|--------------------|---|



### Entertainment

|                   |   |                     |   |
|-------------------|---|---------------------|---|
| Bluetooth Player  | ✓ | Apple Play          | ✓ |
| Android Auto Play | ✓ | Infotainment System | ✓ |
| USB player        | ✓ |                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Condition: Low Visual Dent

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Chip

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             | ✓ | Monogram                     | ✓ |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |

## Engine & Transmission

## Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

## Fuel System

Fuel Tank 

## Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

## Steering, Suspension & Brakes

### Steering

Steering wheel 

### Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

### Suspension

Shock Absorbers 

## Electricals, Controls & Lights

### Keys

Master Key  Spare Key(s) 

### Door Locks

Child Safety Locking 

### Dashboard

Instrument Panel 

### Airbags

Airbags 

Controls  Cruise Control 

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Infotainment Display  | ✓ | OBD Connector           | ✓ |
| Music System          | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| License Plate Light   | ✓ |                         |   |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC Switch               | ✓ |
| AC System Leaks       | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent   | ✓ | Heater                  | ✓ |
| Rear Blower Switch    | ✓ |                         |   |
| Rear Defogger         | ✓ | USB Charging Port       | ✓ |
| Power/ Manual Windows | ✓ |                         |   |

## Interiors & Luggage

|                                |   |   |   |
|--------------------------------|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console                           | ✓ |
| Cup Holder                     | ✓ | Glove Box                                 | ✓ |
| Steering Wheel                 | ✓ | Sunvisor                                  | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement                      | ✓ |
| Seat Belts                     | ✓ | Head Rest                                 | ✓ |
| Door Controls And Trim         | ✓ | Grab Handle                               | ✓ |
| Carpet                         | ✓ | Headliner                                 | ✓ |
| Rear View Mirror               | ✓ | Toolkit                                   | ! |
|                                |   | Jack Availability: Toe Hook Not Available |   |

## Tyres

### Tyres Condition

|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Left Hand Side Front Tyre  |  | Left Hand Side Rear Tyre  |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |   |

### Life remaining

|                |      |               |      |
|----------------|------|---------------|------|
| LHS Front Tyre | <65% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <55% | RHS Rear Tyre | <75% |
| Spare Tyre     | <75% |               |      |



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE