



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 SUZUKI JIMNY

GLX | 28,650 KM

VIN: MA3JC7D22R0157135

## Car highlights



### Low Mileage

This car has been driven less than 15,000 km  
a year



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>28650</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Four Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel Efficiency	<b>13.3 km/L mileage</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Black</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>4 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MA3JC7D22R0157135</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Steering Mounted Audio Controls	
Rear Defogger	
Steering Column Adjuster	
 <b>Exteriors</b>	

Fog Light Front		LED Headlights	
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Curtain Shield	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 <b>Performance</b>			
Hill Descent Control			
 <b>Entertainment</b>			
Bluetooth Player		Apple Play	
Android Auto Play		Infotainment System	
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Panel: Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Condition: Light Scuffing

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip			
Mark>5mm, Passenger Side/Stone Chip	!	Rear Windshield	✓
Mark>8mm			
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags			
Controls		Cruise Control	
Infotainment Display		OBD Connector	
Music System		Camera	
Lights			
Headlight		Interior Lights	
Tail Light Cluster		License Plate Light	
Fog Lights			
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Parking Sensors		Rear Defogger	
USB Charging Port		Power/ Manual Windows	

## **Interiors & Luggage**

Dashboard And Instrument Panel		Central Console	
Glove Box		Steering Wheel Color Faded	
Sunvisor		Seat Upholstery	
Manual Seat Movement		Seat Belts	
Head Rest		Door Controls And Trim	
Grab Handle		Carpet	
Headliner		Rear View Mirror	
Toolkit			

 **Tyres**

## Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



## Life remaining

LHS Front Tyre

&lt;65%

LHS Rear Tyre

&lt;55%

RHS Front Tyre

&lt;65%

RHS Rear Tyre

&lt;75%

Spare Tyre

&lt;85%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE