



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 MAZDA CX 5**

**GL | 66,778 KM**

VIN: JM7KFAWL8R0898042

## Car highlights



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	<b>66778</b>	 Specs	<b>Yes</b>
 Engine	<b>2.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Silver</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>JM7KFAWL8R0898042</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Central Armrest	
 <b>Safety &amp; Security</b>	

Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Curtain Shield	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	

 **Entertainment**

Bluetooth Player		Apple Play	
Android Auto Play		USB Charging Port	
Infotainment System		USB player	

 **Exteriors**

LED Headlights		
----------------	---	--

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Moulding: Low Visual Dent < 30mm

Rear left door



Rear right door



Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender



Right Fender



Condition: Low Visual Dent

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Dent < 50mm, Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Wheel cover		Antenna	
Grill Condition			
Scuffing > 50mm		Monogram	
Window Glass		Wiper	
Panel Condition			

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags			
Controls		Cruise Control	
Infotainment Display		OBD Connector	
Navigation System		Music System	
Camera			
Lights			
Headlight		Interior Lights	
Tail Light Cluster		License Plate Light	
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Rear Blower Switch			
Rear Defogger		USB Charging Port	
Power/ Manual Windows			

## **Interiors & Luggage**

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	

Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<65%

RHS Front Tyre

<55%

RHS Rear Tyre

<65%

Spare Tyre

<65%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE