



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 BMW X2**

**SDRIVE 20i JOY EDITION | 43,474 KM**

VIN: WBAYH3A02P5V66702

## **Car highlights**



### **Low Mileage**

This car has been driven less than 15,000 km  
a year



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 43474             |  Specs             | Yes                  |
|  Engine           | 2.0L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 8 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number      | WBAYH3A02P5V66702 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                             |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                             |                                                                                       |
| Cruise Control                                                                                                       |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls                                                                                      |  | Power Folding Mirrors       |  |
| Rear Defogger                                                                                                        |  | Central Armrest             |  |
| Automatic Headlights                                                                                                 |  | Steering Column Adjuster    |  |
|  <b>Safety &amp; Security</b>     |                                                                                     |                             |                                                                                       |

|                                                                                                        |   |                       |   |
|--------------------------------------------------------------------------------------------------------|---|-----------------------|---|
| Parking Sensors Front                                                                                  | ✓ | Parking Sensors Rear  | ✓ |
| Auto Park Assist                                                                                       | ✓ | Reverse Camera        | ✓ |
| Traction Control                                                                                       | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front                                                                                    | ✓ | ABS                   | ✓ |
| Central Locking                                                                                        | ✓ | Child Safety Locking  | ✓ |
|  <b>Exteriors</b>     |   |                       |   |
| Running Lights                                                                                         | ✓ | Rear Bumper Spoiler   | ✓ |
| LED Headlights                                                                                         | ✓ |                       |   |
|  <b>Entertainment</b> |   |                       |   |
| Bluetooth Player                                                                                       | ✓ | USB Charging Port     | ✓ |
| Infotainment System                                                                                    | ✓ | USB player            | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                                                                         |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door<br>Panel: Light Scuffing < 50mm                        |  |
| Rear left door  |  | Rear right door<br>Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm |  |

### Fenders Condition

|                                          |                                                                                   |                                                    |                                                                                     |
|------------------------------------------|-----------------------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------------------------------------|
| Left Fender<br>Condition: Light Scuffing |  | Right Fender<br>Right Fender: Dent, Paint Chip-off |  |
|------------------------------------------|-----------------------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|             |                                                                                     |
|-------------|-------------------------------------------------------------------------------------|
| Rear Bumper |  |
|-------------|-------------------------------------------------------------------------------------|

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Pillars Condition

|                            |                                                                                     |                             |                                                                                       |
|----------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|
| Left A Pillar              |  | Right A Pillar              |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |
| Right A to B Pillar        |  | Left B Pillar               |  |

|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Antenna                     | ✓ | Grill Condition              | ⓘ |
|                             |   | Light Scuffing < 50mm        |   |
| Monogram                    | ✓ | Window Glass                 | ✓ |
| Wiper                       | ✓ |                              |   |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |

## Engine & Transmission

Engine

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition | ✓ |
| Radiator Coolant               | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Tank                      | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| Transmission Fluid             | ✓ |                    |   |

## **Steering, Suspension & Brakes**

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Suspension             |   |                       |   |
| Shock Absorbers        | ✓ |                       |   |

## **Electricals, Controls & Lights**

|                      |   |                |   |
|----------------------|---|----------------|---|
| Keys                 |   |                |   |
| Master Key           | ✓ | Spare Key(s)   | ✓ |
| Door Locks           |   |                |   |
| Child Safety Locking | ✓ |                |   |
| Dashboard            |   |                |   |
| Instrument Panel     | ✓ |                |   |
| Airbags              |   |                |   |
| Airbags              | ✓ |                |   |
| Controls             | ✓ | Cruise Control | ✓ |

|                      |   |                         |   |
|----------------------|---|-------------------------|---|
| Infotainment Display | ✓ | OBD Connector           | ✓ |
| Music System         | ✓ | Camera                  | ✓ |
| Lights               |   |                         |   |
| Headlight            | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster   | ✓ | Daylight Running Lights | ✓ |
| License Plate Light  | ✓ |                         |   |
| Air Conditioning     |   |                         |   |
| AC Cooling           | ✓ | AC Switch               | ✓ |
| AC System Leaks      | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent  | ✓ | Heater                  | ✓ |
| Parking Sensors      | ✓ | Rear Defogger           | ✓ |
| USB Charging Port    | ✓ | Power/ Manual Windows   | ✓ |
| Memory Seats         | ✓ |                         |   |



## Interiors & Luggage

|                                |   |                      |   |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console      | ✓ |
| Cup Holder                     | ✓ | Glove Box            | ✓ |
| Steering Wheel                 | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                     | ✓ | Head Rest            | ✓ |
| Door Controls And Trim         | ✓ | Grab Handle          | ✓ |
| Carpet                         | ✓ | Headliner            | ✓ |
| Rear View Mirror               | ✓ | Toolkit              | ✓ |



## Tyres

|                            |                                                                                   |                           |                                                                                     |
|----------------------------|-----------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| Tyres Condition            |                                                                                   |                           |                                                                                     |
| Left Hand Side Front Tyre  |  | Left Hand Side Rear Tyre  |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Life remaining             |                                                                                   |                           |                                                                                     |
| LHS Front Tyre             | <75%                                                                              | LHS Rear Tyre             | <75%                                                                                |
| RHS Front Tyre             | <75%                                                                              | RHS Rear Tyre             | <75%                                                                                |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE