



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 TOYOTA RAIZE

G | 102,293 KM

VIN: MHKAA1BA0PJ057841

Car highlights



Boosted Engine

This car has a Boosted Engine



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

| | | | |
|--|--------------------------|---|-----------------------------|
|  Kilometers | 102293 |  Specs | Yes |
|  Engine | 1.0L |  Option Type | Fully Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 1 Keys |
|  VIN number | MHKAA1BA0PJ057841 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Safety & Security | | | |
|---|---|---------------------|---|
| Parking Sensors Rear |  | Reverse Camera |  |
| Traction Control |  | Airbag Driver Front |  |
| ABS |  | Central Locking |  |
| Child Safety Locking |  | | |
|  Exteriors | | | |

| | | | |
|----------------------------------|---|----------------------|---|
| Running Lights |  | Rear Bumper Spoiler |  |
| LED Headlights |  | | |
| Comfort & Convenience | | | |
| Steering Mounted Audio Controls |  | Rear Defogger |  |
| Central Armrest |  | Automatic Headlights |  |
| Steering Column Adjuster |  | | |
| Entertainment | | | |
| Bluetooth Player |  | USB Charging Port |  |
| Infotainment System |  | USB player |  |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Low Visibility



Dent < 30mm

Rear left door



Rear right door

Panel: Light Scuffing < 50mm



Fenders Condition

Left Fender



Right Fender



Condition: Light Scuffing

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Bonnet: Light Scuffing < 50mm

Trunk Condition

Trunk



Door Trim: Scuff/ Disfiguration < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



| | | | |
|-----------------------------|---|------------------------------|---|
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | | | ! |
| Fair Use Wear/Crack<5mm | | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Turbocharger/ Supercharger  Radiator Condition 

Radiator Coolant 

Fuel System

Fuel Tank 

Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

Suspension

Shock Absorbers 

Electricals, Controls & Lights

Keys

Master Key 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

| | | | |
|-----------------------|--|-------------------------|--|
| Airbags | | | |
| Controls | | Infotainment Display | |
| OBD Connector | | Music System | |
| Camera | | | |
| Lights | | | |
| Headlight | | Interior Lights | |
| Tail Light Cluster | | Daylight Running Lights | |
| License Plate Light | | | |
| Air Conditioning | | | |
| AC Cooling | | AC Switch | |
| AC System Leaks | | Center AC Vent | |
| Front Right AC Vent | | Heater | |
| Rear Defogger | | USB Charging Port | |
| Power/ Manual Windows | | | |

Interiors & Luggage

| | | | |
|--|--|--|--|
| Dashboard And Instrument Panel | | Central Console | |
| Glove Box | | Steering Wheel Steering Wheel Fair Use Wear | |
| Sunvisor | | | |
| Left: Sunvisor LHS RHS Minor Smudge | | Seat Upholstery | |
| Manual Seat Movement | | Seat Belts | |
| Head Rest | | Door Controls And Trim | |
| Grab Handle | | Carpet | |
| Headliner | | Rear View Mirror De Silvered Mirror<10% | |
| Rear Left: Smudge/Disfiguration | | | |



Tyres

Tyres Condition

| | | | |
|----------------------------|--|---------------------------|--|
| Left Hand Side Front Tyre | | Left Hand Side Rear Tyre | |
| Right Hand Side Front Tyre | | Right Hand Side Rear Tyre | |
| Spare Tyre | | | |

Life remaining

| | | | |
|----------------|------|---------------|------|
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <75% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE