



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 HYUNDAI ACCENT

SMART | 32,725 KM

VIN: MALC741C3PM384655

Car highlights



Low Mileage

This car has been driven less than 15,000 km
a year



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	32725	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel Efficiency	16.2 km/L mileage
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	MALC741C3PM384655		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Cruise Control	
Rear Defogger	
Steering Column Adjuster	
 Safety & Security	
Parking Sensors Rear	
Reverse Camera	

Traction Control	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		

 **Entertainment**

Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

 **Exteriors**

Halogen Headlights	✓	
--------------------	---	--

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender

Condition: Low Visual Dent, Light Scuffing



Right Fender: Light Scuffing

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent, Light Scuffing

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Dent > 50mm, Crack/

Misaligned

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor			
Condition: Rear End Panel Repaired	!	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition			
Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

Fuel System

Fuel Tank 

Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

Suspension

Shock Absorbers 

Electricals, Controls & Lights

Keys

Master Key 

Button Faded

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls  Cruise Control 

Infotainment Display	✓	OBD Connector	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	
Seat Upholstery	!	Left: Sunvisor LHS Minor Crack/Fair Use	!
Driver Seat: Minor Smudge/ Cracks		Wear, Sunvisor RHS Minor Crack/Damage	
Seat Belts	✓	Manual Seat Movement	✓
Door Controls And Trim	✓	Head Rest	✓
Carpet	!	Grab Handle	✓
Front Left Floor Mat: Smudge/Burn/Crack		Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<85%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE