



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2025 RENAULT DUSTER

SE | 15,756 KM

VIN: VF1HSRMX3SA091267

## Car highlights



### Great condition

Car has low imperfections



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Android Auto

Enjoy your drive with Android Auto



### Amazing Comfort

Power driver seat

## Basic Details

|  |                          |   |                            |
|--|--------------------------|---|----------------------------|
|  Kilometers       | <b>15756</b>             |  Specs             | <b>Yes</b>                 |
|  Engine           | <b>1.6L</b>              |  Option Type       | <b>Semi Loaded</b>         |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>Front Wheel Drive</b>   |
|  Body Type        | <b>SUV</b>               |  Fuel Efficiency   | <b>15.3 km/L mileage</b>   |
|  Wheel Type       | <b>Alloy Wheels</b>      |  Exterior Color    | <b>Exterior Color Grey</b> |
|  Interior Trim    | <b>Fabric Trim</b>       |  Number of Airbags | <b>4 Airbags</b>           |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>1 Keys</b>              |
|  VIN number      | <b>VF1HSRMX3SA091267</b> |   |                            |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |
|--|---|
|  <b>Comfort &amp; Convenience</b> |   |
| Climate Control AC   |    |
| Steering Mounted Audio Controls  |    |
| Central Armrest  |    |
|  <b>Exteriors</b>                 |   |
| Fog Light Front  |    |
|  |  |
| Roof Rails   |  |

|                              |   |                      |   |
|------------------------------|---|----------------------|---|
| Running Lights               |   | LED Headlights       |   |
| Halogen Headlights           |  |                      |   |
| <b>Safety &amp; Security</b> |   |                      |   |
| Navigation                   |  | Parking Sensors Rear |  |
| Reverse Camera               |  | Airbag Driver Front  |  |
| ABS                          |  | Central Locking      |  |
| Child Safety Locking         |  |                      |   |
| <b>Entertainment</b>         |   |                      |   |
| Bluetooth Player             |  | Android Auto Play    |  |
| Infotainment System          |  | USB player           |  |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Panel: Low Visual Dent < 30mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



|                                       |   |                              |   |
|---------------------------------------|---|------------------------------|---|
| Right A to B Pillar                   | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                | ✓ |
| Running Board Condition               |   |                              |   |
| Left Running Board                    | ✓ | Right Running Board          | ✓ |
| Sunroof Glass Condition (If Equipped) |   |                              |   |
| Sun Roof Glass                        | ✓ |                              |   |
| Windshield Condition                  |   |                              |   |
| Front Windshield                      | ✓ | Rear Windshield              | ✓ |
| Structural Assessment                 |   |                              |   |
| Chassis Condition                     | ✓ | Apron                        | ✓ |
| Boot Floor                            | ✓ | Firewall Condition           | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                              |   |                              |   |
| Cowl Top                              | ✓ |                              |   |
| Rear View Mirror Condition            |   |                              |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror                     | ✓ |                              |   |
| Alloy Wheel/ Rim                      |   |                              |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |                              |   |
| Antenna                               | ✓ | Grill Condition              | ✓ |
| Monogram                              | ✓ | Window Glass                 | ✓ |
| Wiper                                 | ✓ |                              |   |
| Panel Condition                       |   |                              |   |

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

|                       |  |                         |  |
|-----------------------|--|-------------------------|--|
| Airbags               |  |                         |  |
| Controls              |  | Cruise Control          |  |
| Infotainment Display  |  | OBD Connector           |  |
| Music System          |  |                         |  |
| Sunroof Operation     |  |                         |  |
| Sunroof               |  |                         |  |
| Camera                |  |                         |  |
| Lights                |  |                         |  |
| Headlight             |  | Interior Lights         |  |
| Tail Light Cluster    |  | Daylight Running Lights |  |
| License Plate Light   |  | Fog Lights              |  |
| Air Conditioning      |  |                         |  |
| AC Cooling            |  | AC Switch               |  |
| AC System Leaks       |  | Center AC Vent          |  |
| Front Right AC Vent   |  | Heater                  |  |
| Rear Blower Switch    |  |                         |  |
| Rear Defogger         |  | USB Charging Port       |  |
| Power/ Manual Windows |  |                         |  |

## **Interiors & Luggage**

|                                |  |                        |  |
|--------------------------------|--|------------------------|--|
| Dashboard And Instrument Panel |  | Central Console        |  |
| Glove Box                      |  | Steering Wheel         |  |
| Sunvisor                       |  | Seat Upholstery        |  |
| Manual Seat Movement           |  | Seat Belts             |  |
| Head Rest                      |  | Door Controls And Trim |  |

|             |  |   |  |
|-------------|--|---|--|
| Grab Handle |  | Carpet                                    |  |
| Headliner   |  | Rear View Mirror                          |  |
| Toolkit     |  | Jack Availability: Toe Hook Not Available |  |

## Tyres

### Tyres Condition

|                            |  |                           |  |  |
|----------------------------|--|---------------------------|--|--|
| Left Hand Side Front Tyre  |  | Left Hand Side Rear Tyre  |  |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |  |
| Spare Tyre                 |  |                           |  |  |

### Life remaining

|                |      |               |      |  |
|----------------|------|---------------|------|--|
| LHS Front Tyre | <65% | LHS Rear Tyre | <75% |  |
| RHS Front Tyre | <65% | RHS Rear Tyre | <75% |  |
| Spare Tyre     | <55% |               |      |  |



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE