



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 MITSUBISHI OUTLANDER

GLX MID LINE | 61,788 KM

VIN: JE4LZU1W0PZ702490

## Car highlights



### Four wheel drive

This car has a Four wheel drive



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>61788</b>	 Specs	<b>Yes</b>
 Engine	<b>2.4L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Four Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Blue</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>7 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>JE4LZU1W0PZ702490</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Central Armrest	
 <b>Exteriors</b>	

Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
Halogen Headlights			

#### **Performance**

Paddle Shift		Differential Locks	
--------------	---	--------------------	---

#### **Safety & Security**

Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			

#### **Entertainment**

Bluetooth Player		USB Charging Port	
Infotainment System		USB player	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Scuffing

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off > 5mm

Fenders Condition

Left Fender



Right Fender



Condition: Low Visual Dent

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent, Acid Marks/ Bird Dropping

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Alloy Wheel/ Rim			
Left Rear Alloy/ Rim		Right Front Alloy/ Rim	
Right Rear Alloy/ Rim		Spare Alloy/ Rim Condition	
Wheel cover		Antenna	
Grill Condition		Monogram	
Window Glass		Wiper	
		Front Left: Crack/ Fair Use Wear	
Panel Condition			
Rear Trunk Panel			

## Engine & Transmission

### Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

### Fuel System

Fuel Tank 

### Transmission Operation

Gear Shifting  Gear shift 

Drive Axle  Transmission Fluid 

## Steering, Suspension & Brakes

### Steering

Steering wheel 

### Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

### Suspension

Shock Absorbers 

## Electricals, Controls & Lights

### Keys

Master Key  Spare Key(s) 

### Door Locks

Child Safety Locking 

### Dashboard

Instrument Panel 

### Airbags

Airbags 

Controls		Cruise Control	
Infotainment Display		OBD Connector	
Music System		Camera	
Lights			
Headlight		Interior Lights	
Left: Low Brightness lamps			
Tail Light Cluster		Daylight Running Lights	
Right Tail Lamp: Crack / Fair Use Wear > 5mm			
License Plate Light		Fog Lights	
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Rear Blower Switch			
Crack			
Parking Sensors		Rear Defogger	
USB Charging Port		Power/ Manual Windows	
Memory Seats			

## Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Passenger Seat: Cigarette Burn > 10mm			
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	

Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<65%

RHS Front Tyre

<55%

RHS Rear Tyre

<65%

Spare Tyre

<65%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE