



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 FORD EDGE

SE | 43,952 KM

VIN: 2FMPK3G95NBB02247

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Apple play

Enjoy your drive with apple play

Convenience Fee Applicable















Extra fee ranging from AED 2.5K-4K
applicable



Amazing Comfort










Power driver seat




Basic Details

| | | | |
|--|--------------------------|---|-----------------------------|
|  Kilometers | 43952 |  Specs | Yes |
|  Engine | 2.0L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV | Fuel Efficiency | 11.8 km/L mileage |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Fabric Trim |  Number of Airbags | 7 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | 2FMPK3G95NBB02247 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|-------------------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Power Window front - Drivers Side |  | Power Window front - Passenger Side |  |
| Power Windows Rear |  | | |
|  Safety & Security | | | |
| Lane Departure Warning System |  | Parking Sensors Rear |  |

| | | | |
|--|---|-----------------------|---|
| Reverse Camera |  | Blind Spot Monitor |  |
| Collision Warning System |  | Airbag Curtain Shield |  |
| Airbag Knees |  | Airbag Driver Front |  |
| ABS |  | | |
|  Exteriors | | | |
| Running Lights |  | Rear Bumper Spoiler |  |
|  Entertainment | | | |
| Bluetooth Player |  | Apple Play |  |
| Android Auto Play |  | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper

Rear Bumper: Chip < 8mm



Hood Condition

Hood



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Grill Condition



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



Steering, Suspension & Brakes

Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Dashboard

Instrument Panel



Controls



Infotainment Display



Music System



Camera



Lights

| | | | |
|-----------------------|---|--------------------|---|
| Headlight | ✓ | Tail Light Cluster | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC System Leaks | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|----------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |
| LHS Front Tyre | <35% | LHS Rear Tyre | <35% |
| RHS Front Tyre | <35% | RHS Rear Tyre | <35% |
| Spare Tyre | <35% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE