



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 CHANGAN CS85

LIMITED | 76,010 KM

Car highlights



Manufacturer warranty

Till 20/05/2028; Extended warranty available



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

 Kilometers	76010	 Specs	Yes
 Engine	2.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	LS4ASE2A7PP142026		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Adaptive cruise control		360 degree Camera	
Lane Departure Warning System		Parking Sensors Front	
Parking Sensors Rear		Auto Park Assist	
Reverse Camera		Blind Spot Monitor	
Collision Warning System		Front Camera	

Side Camera	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
 Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Ventilated Seat	✓
Power Tailgate/ Power Trunk	✓	Power Windows Rear	✓
 Exteriors			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓		
 Performance			
Hill Descent Control	✓		
 Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Condition: Low Visual Dent

Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent

Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Infotainment Display	✓

Music System	✓	Camera	✓
Lights			
Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Entertainment		Power/ Manual Windows	✓
Left Seat LCD: Damaged	!		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Steering Wheel	✓
Headliner	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%
Spare Tyre	<35%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE