



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2025 MG ZS

STD | 25,359 KM

VIN: LSJW74U30SZ025575

## Car highlights



### Great condition

Car has low imperfections



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

## Basic Details

|  |                          |   |                             |
|--|--------------------------|---|-----------------------------|
|  Kilometers       | <b>25359</b>             |  Specs             | <b>Yes</b>                  |
|  Engine           | <b>1.5L</b>              |  Option Type       | <b>Basic</b>                |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>Front Wheel Drive</b>    |
|  Body Type        | <b>SUV</b>               | Fuel Efficiency   | <b>17.2 km/L mileage</b>    |
|  Wheel Type       | <b>Alloy Wheels</b>      |  Exterior Color    | <b>Exterior Color White</b> |
|  Interior Trim    | <b>Fabric Trim</b>       |  Number of Airbags | <b>2 Airbags</b>            |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>2 Keys</b>               |
|  VIN number      | <b>LSJW74U30SZ025575</b> |   |                             |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |  |
|--|---|--|
|  <b>Comfort &amp; Convenience</b> |   |  |
| Cruise Control   |  |  |
|  <b>Safety &amp; Security</b>     |   |  |
| Parking Sensors Rear   |  | Reverse Camera  |
| Airbag Driver Front  |  | ABS             |
|  <b>Exteriors</b>                 |   |  |

|  |   |
|--|---|
| Roof Rails             | Running Lights  |
|  <b>Performance</b>   |   |
| Hill Descent Control  |   |
|  <b>Entertainment</b> |   |
| Bluetooth Player      | Apple Play     |
| Android Auto Play     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front right door



Rear left door



Rear right door



Panel: Paint Defect, Dent > 30mm

### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Scuffing/ Scratch



### Rear Bumper Condition

Rear Bumper



### Hood Condition

Hood



### Roof Condition

Roof



### Running Board Condition

Left Running Board



Right Running Board



### Windshield Condition

Front Windshield



Rear Windshield



### Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

|                          |  |                       |  |
|--------------------------|--|-----------------------|--|
| Cowl Top                 |  |                       |  |
| Alloy Wheel/ Rim         |  |                       |  |
| Left Front Alloy/ Rim    |  |                       |  |
| Rim: Alloy Edge Scuffing |  | Left Rear Alloy/ Rim  |  |
| Right Front Alloy/ Rim   |  | Right Rear Alloy/ Rim |  |
| Panel Condition          |  |                       |  |
| Rear Trunk Panel         |  |                       |  |

## Engine & Transmission

|                                |  |                    |  |
|--------------------------------|--|--------------------|--|
| Engine                         |  |                    |  |
| Engine Body                    |  | Engine Performance |  |
| Engine Oil (Condition & Level) |  | Exhaust System     |  |
| Radiator Condition             |  | Radiator Coolant   |  |
| Transmission Operation         |  |                    |  |
| Gear Shifting                  |  | Drive Axle         |  |

## Steering, Suspension & Brakes

|                 |  |                       |  |
|-----------------|--|-----------------------|--|
| Brake System    |  |                       |  |
| Parking Brake   |  | Brake Master Cylinder |  |
| Brake Fluid     |  |                       |  |
| Suspension      |  |                       |  |
| Shock Absorbers |  |                       |  |

## Electricals, Controls & Lights

|                  |  |                      |  |
|------------------|--|----------------------|--|
| Keys             |  |                      |  |
| Master Key       |  |                      |  |
| Dashboard        |  |                      |  |
| Instrument Panel |  |                      |  |
| Controls         |  | Infotainment Display |  |
| Music System     |  | Camera               |  |

## Lights

|                         |   |                    |   |
|-------------------------|---|--------------------|---|
| Headlight               | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ |                    |   |
| Air Conditioning        |   |                    |   |
| AC Cooling              | ✓ | AC System Leaks    | ✓ |
| Power/ Manual Windows   | ✓ |                    |   |

## Interiors & Luggage

|                                |   |                |   |
|--------------------------------|---|----------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner                      | ✓ | Toolkit        | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <73% | LHS Rear Tyre             | <73% |
| RHS Front Tyre             | <73% | RHS Rear Tyre             | <73% |
| Spare Tyre                 | <73% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE