

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 MITSUBISHI ATTRAGE

GLX HIGHLINE | 34,968 KM

Car highlights

Fuel Efficient

Fuel efficient with 20.2 km/L

Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	34968	Specs	Yes
Engine	1.2L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SEDAN	Fuel Efficiency	20.2 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Silver
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	MMDAFT6J4PH002481		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Exteriors			
Fog Light Front	✓	Rear Bumper Spoiler	✓
Comfort & Convenience			
Cruise Control	✓		
Entertainment			
Bluetooth Player	✓		

Safety & Security

Airbag Driver Front ✓	ABS ✓

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	!	Rear left door	✓
Rear right door Panel: Light Scuffing < 50mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Dent, Light Scuffing	!

Rear Bumper Condition

Rear Bumper Rear Bumper: Dent > 50mm, Light Scuffing < 80mm	!

Hood Condition

Hood Bonnet: Light Scuffing < 50mm	!

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition Light Scuffing < 50mm	!		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Infotainment Display	✓

Music System	✓		

Lights

Headlight	✓	Tail Light Cluster	✓

Air Conditioning

AC Cooling	✓	AC System Leaks	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Steering Wheel	✓
Headliner	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<35%	LHS Rear Tyre	<35%
RHS Front Tyre	<35%	RHS Rear Tyre	<35%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE