**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.

**2023 HYUNDAI SANTA FE**

**SMART | 82,811 KM**

VIN: KMHS281K0PU446956

## Car highlights

### Cruise control

Cruise control to drive with ease & comfort

### Great Parking Assistance

Reverse Camera, Parking Sensors Rear

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

### Apple play

Enjoy your drive with apple play

### Amazing Comfort

Power driver seat

## Basic Details

| | |
|---|---|
| Kilometers | 82811 |
| Engine | 2.5L |
| Transmission | Automatic |
| Body Type | SUV |
| Wheel Type | Alloy Wheels |
| Interior Trim | Fabric Trim |
| Seating Capacity | 7 Seats |
| VIN number | KMHS281K0PU446956 |
| Specs | Yes |
| Option Type | Basic |
| Drive | Front Wheel Drive |
| Fuel | Petrol |
| Exterior Color | Exterior Color White |
| Number of Airbags | 2 Airbags |
| Number of keys | 1 Keys |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| **Comfort & Convenience** | | | |
|---|---|---|---|
| Cruise Control | ✓ | Power Window front - Drivers Side | ✓ |
| Power Window front - Passenger Side | ✓ | Power Windows Rear | ✓ |
| **Safety & Security** | | | |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Airbag Driver Front | ✓ | Airbag Passenger Front | ✓ |

| Exteriors | | | |
|---|---|---|---|
| Roof Rails | ✓ | Running Lights | ✓ |
| Rear Bumper Spoiler | ✓ | | |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | | |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed** ✓

## Exterior

Doors condition

| | | | |
|---|---|---|---|
| Front right door<br>Panel: Low Visibility Dent < 30mm | ! | Rear left door | ✓ |
| Rear right door<br>Panel: Low Visual Dent < 30mm | ! | | |

Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender | ✓ | Right Fender | ✓ |

Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | ✓ |

Hood Condition

| | |
|---|---|
| Hood | ✓ |

Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

Sunroof Glass Condition (If Equipped)

| | |
|---|---|
| Sun Roof Glass | ✓ |

Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Head Light Support Condition | ✓ | | |

Cowl Top

| | | | |
|---|---|---|---|
| Cowl Top | ✓ | | |
| **Alloy Wheel/ Rim** | | | |
| Left Front Alloy/ Rim<br>Rim: Alloy Edge Scuffing | ! | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim<br>Rim: Alloy Face/Light Scuffing | ! |
| **Panel Condition** | | | |
| Rear Trunk Panel | ✓ | | |

## Engine & Transmission

| | | | |
|---|---|---|---|
| **Engine** | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| **Transmission Operation** | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |

## Steering, Suspension & Brakes

| | | | |
|---|---|---|---|
| **Brake System** | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid | ✓ | | |
| **Suspension** | | | |
| Shock Absorbers | ✓ | | |

## Electricals, Controls & Lights

| | | | |
|---|---|---|---|
| **Keys** | | | |
| Master Key | ✓ | | |
| **Dashboard** | | | |
| Instrument Panel | ✓ | | |
| Controls | ✓ | Infotainment Display | ✓ |
| Music System | ✓ | Camera | ✓ |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights<br>Right DRL: Low Brightness | ! | | |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | AC System Leaks | ✓ |
| Rear Left AC Vent | ✓ | | |
| Power/ Manual Windows | ✓ | | |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel | ✓ | Headliner | ✓ |
| Toolkit | ✓ | | |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <35% | LHS Rear Tyre | <35% |
| RHS Front Tyre | <35% | RHS Rear Tyre | <35% |
| Spare Tyre | <35% | | |

**A whole new world of cars**

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE