



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 NISSAN SUNNY**

**SV | 99,348 KM**

VIN: MDHBN7AD6PG318209

## **Car highlights**

### **Fuel Efficient**

Fuel efficient with 18.0 km/L



### **Great Parking Assistance**

Parking Sensors Rear

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

## Basic Details

|  |                          |   |                             |
|--|--------------------------|---|-----------------------------|
|  Kilometers       | <b>99348</b>             |  Specs             | <b>Yes</b>                  |
|  Engine           | <b>1.5L</b>              |  Option Type       | <b>Basic</b>                |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>Front Wheel Drive</b>    |
|  Body Type        | <b>SEDAN</b>             | Fuel Efficiency   | <b>18.0 km/L mileage</b>    |
|  Wheel Type       | <b>Steel Wheels</b>      |  Exterior Color    | <b>Exterior Color White</b> |
|  Interior Trim    | <b>Fabric Trim</b>       |  Number of Airbags | <b>2 Airbags</b>            |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>2 Keys</b>               |
|  VIN number      | <b>MDHBN7AD6PG318209</b> |   |                             |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                                     |   |
|--|---|-------------------------------------|---|
|  <b>Safety &amp; Security</b>     |   |                                     |   |
| Parking Sensors Rear   |  | Airbag Driver Front                 |  |
| ABS  |  |                                     |   |
|  <b>Comfort &amp; Convenience</b> |   |                                     |   |
| Power Window front - Drivers Side  |  | Power Window front - Passenger Side |  |
|  <b>Entertainment</b>             |   |                                     |   |

Bluetooth Player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

#### Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm 

Rear left door 

#### Rear right door

Panel: Low Visual Dent < 30mm, Scuffing > 50mm 

### Fenders Condition

#### Left Fender

Condition: Low Visual Dent, Light Scuffing 

Right Fender 

### Quarter Panels Condition

#### Left Quarter Panel



#### Right Quarter Panel

Condition: Dent 

### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Paint Faded, Fully Repainted 

### Hood Condition

#### Hood

Bonnet: Dent > 30mm 

### Running Board Condition

#### Left Running Board



#### Right Running Board



### Windshield Condition

#### Front Windshield



#### Rear Windshield



### Structural Assessment

#### Chassis Condition



#### Apron



#### Boot Floor



#### Firewall Condition



#### Head Light Support Condition



#### Cowl Top

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Cowl Top               | ✓ |                       |   |
| Alloy Wheel/ Rim       |   |                       |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition        | ✓ |                       |   |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

### Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

### Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Steering        |   |                       |   |
| Steering wheel  | ✓ |                       |   |
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

### Electricals, Controls & Lights

|                  |   |
|------------------|---|
| Keys             |   |
| Master Key       | ✓ |
| Dashboard        |   |
| Instrument Panel | ✓ |

|                         |   |                      |   |
|-------------------------|---|----------------------|---|
| Controls                | ✓ | Infotainment Display | ✓ |
| Music System            | ✓ |                      |   |
| Lights                  |   |                      |   |
| Headlight               | ✓ | Tail Light Cluster   | ✓ |
| Daylight Running Lights | ✓ |                      |   |
| Air Conditioning        |   |                      |   |
| AC Cooling              | ✓ | AC System Leaks      | ✓ |

### Interiors & Luggage

|                                |   |                |   |
|--------------------------------|---|----------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner                      | ✓ | Toolkit        | ✓ |

### Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <73% | LHS Rear Tyre             | <73% |
| RHS Front Tyre             | <73% | RHS Rear Tyre             | <73% |
| Spare Tyre                 | <35% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE