



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 BMW X2

SDRIVE 20I JOY EDITION | 68,629 KM

VIN: WBAYH3A08P5V72990

## Car highlights

### Service History

Service history available



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>68629</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Blue</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>8 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>WBAYH3A08P5V72990</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Power Window front - Drivers Side	
Power Window front - Passenger Side		Power Windows Rear	
 <b>Safety &amp; Security</b>			
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Airbag Curtain Shield	

Airbag Driver Front		Airbag Passenger Front	
ABS			
 <b>Exteriors</b>			
Running Lights			
 <b>Entertainment</b>			
Bluetooth Player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

#### Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm 

Rear left door 

#### Rear right door

Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm 

### Fenders Condition

Left Fender 

Right Fender  
Right Fender: Scuffing 

### Quarter Panels Condition

Left Quarter Panel 

Right Quarter Panel 

### Rear Bumper Condition

Rear Bumper  
Rear Bumper: Light Scuffing < 80mm 

### Hood Condition

#### Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm 

### Running Board Condition

Left Running Board 

Right Running Board 

### Windshield Condition

Front Windshield 

Rear Windshield 

### Structural Assessment

Chassis Condition 

Apron 

Boot Floor 

Firewall Condition 

Head Light Support Condition 

Cowl Top

Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Grill Condition

Light Scuffing < 50mm



Panel Condition

Rear Trunk Panel

Scratch



---

## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



---

## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Shock Absorbers



---

## Electricals, Controls & Lights

Keys

Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Infotainment Display	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Tail Light Cluster Left Tail Lamp: Light Scuffing < 50mm	!
Daylight Running Lights Right DRL: Low Brightness	!		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Power/ Manual Windows	✓		

### Interiors & Luggage

Dashboard And Instrument Panel Dashboard Upholstery: Minor Color Dullness	!	Steering Wheel Steering Wheel Fair Use Wear	!
Headliner	✓	Toolkit	✓

### Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Life remaining			
LHS Front Tyre	<90%	LHS Rear Tyre	<55%
RHS Front Tyre	<90%	RHS Rear Tyre	<55%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE