



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 MINI COOPER

STD | 51,407 KM

VIN: WMW31DK09R2U63218

Car highlights

Service History

Service history available



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	51407	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	Fuel Efficiency	16.15 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WMW31DK09R2U63218		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Power Window front - Drivers Side	
Power Window front - Passenger Side		Power Windows Rear	
 Safety & Security			
Navigation		Parking Sensors Rear	
Reverse Camera		Airbag Sides	

Airbag Curtain Shield	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
 Exteriors			
Running Lights	✓	Rear Bumper Spoiler	✓
 Entertainment			
Bluetooth Player	✓	Apple Play	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim		
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim ✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim ✓
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Turbocharger/ Supercharger	✓	Radiator Condition ✓
Radiator Coolant	✓	
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓

Steering, Suspension & Brakes

Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Fluid	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys		
Master Key	✓	
Dashboard		
Instrument Panel	✓	
Controls	✓	Infotainment Display ✓
Music System	✓	Camera ✓
Lights		

Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights			
Right DRL: Low Brightness, Lamps Are Not Working	!		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Steering Wheel	✓
Headliner	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Life remaining			
LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE