



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 MAZDA 6

S | 104,661 KM

## Car highlights



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 104661            |  Specs             | Yes                 |
|  Engine           | 2.5L              |  Option Type       | Basic               |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 14.0 km/L mileage   |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 6 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | JM7GL4S36P1486828 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                      |  |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Power Windows Rear                                                                                                   |  |                                     |                                                                                       |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                     |                                                                                       |
| Parking Sensors Rear                                                                                                 |  | Reverse Camera                      |  |

|                                                                                                        |   |                     |   |
|--------------------------------------------------------------------------------------------------------|---|---------------------|---|
| Airbag Curtain Shield                                                                                  | ✓ | Airbag Driver Front | ✓ |
| Airbag Passenger Front                                                                                 | ✓ | ABS                 | ✓ |
|  <b>Exteriors</b>     |   |                     |   |
| Running Lights                                                                                         | ✓ |                     |   |
|  <b>Entertainment</b> |   |                     |   |
| Bluetooth Player                                                                                       | ✓ |                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

#### Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm



#### Rear left door



#### Rear right door

Panel: Light Scuffing < 50mm



### Fenders Condition

#### Left Fender

Condition: Light Scuffing



#### Right Fender



### Quarter Panels Condition

#### Left Quarter Panel

Condition: Scuffing



#### Right Quarter Panel

Condition: Light Scuffing, Low Visual Dent



### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Paint Faded, Fully Repainted



### Hood Condition

#### Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm



### Running Board Condition

#### Left Running Board



#### Right Running Board

Condition: Light Scuffing < 80mm



### Windshield Condition

#### Front Windshield



#### Rear Windshield



### Structural Assessment

#### Chassis Condition



#### Apron



#### Boot Floor



#### Firewall Condition



#### Head Light Support Condition



|                          |   |                       |
|--------------------------|---|-----------------------|
| Cowl Top                 |   |                       |
| Cowl Top                 | ✓ |                       |
| Alloy Wheel/ Rim         |   |                       |
| Left Front Alloy/ Rim    | ! | Left Rear Alloy/ Rim  |
| Rim: Alloy Edge Scuffing |   | ✓                     |
| Right Front Alloy/ Rim   | ! | Right Rear Alloy/ Rim |
| Rim: Alloy Edge Scuffing |   | ✓                     |
| Grill Condition          | ✓ |                       |
| Panel Condition          |   |                       |
| Rear Trunk Panel         | ✓ |                       |

## Engine & Transmission

|                                |   |                    |
|--------------------------------|---|--------------------|
| Engine                         |   |                    |
| Engine Body                    | ✓ | Engine Performance |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     |
| Radiator Condition             | ✓ | Radiator Coolant   |
| Transmission Operation         |   |                    |
| Gear Shifting                  | ✓ | Drive Axle         |

## Steering, Suspension & Brakes

|                 |   |                       |
|-----------------|---|-----------------------|
| Brake System    |   |                       |
| Parking Brake   | ✓ | Brake Master Cylinder |
| Brake Fluid     | ✓ |                       |
| Suspension      |   |                       |
| Shock Absorbers | ✓ |                       |

## Electricals, Controls & Lights

|                  |   |
|------------------|---|
| Keys             |   |
| Master Key       | ✓ |
| Dashboard        |   |
| Instrument Panel | ✓ |

|                         |   |                      |   |
|-------------------------|---|----------------------|---|
| Controls                | ✓ | Infotainment Display | ✓ |
| Music System            | ✓ | Camera               | ✓ |
| Lights                  |   |                      |   |
| Headlight               | ✓ | Tail Light Cluster   | ✓ |
| Daylight Running Lights | ✓ |                      |   |
| Air Conditioning        |   |                      |   |
| AC Cooling              | ✓ | AC System Leaks      | ✓ |
| Power/ Manual Windows   | ✓ |                      |   |



## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard Upholstery: Minor Color Dullness, Minor Scuffing/ Disfiguration/ Melted



### Steering Wheel

Steering Wheel Fair Use Wear



Headliner



Toolkit



## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<90%

LHS Rear Tyre

<90%

RHS Front Tyre

<90%

RHS Rear Tyre

<90%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE